

The results of nuclide analyses of plutonium in seawater
Fukushima Daiichi Nuclear Power Station

1. Place of Sampling: North-side of intake canals of Units 1-4 of Fukushima Daiichi Nuclear Power Station
2. Analysis Agency: Japan Chemical Analysis Center
3. Results of measurement:

(Unit: mBq/L)

Place of Sampling	Date of Sampling	Pu-238	Pu-239,Pu-240
North-side of intake canals of Units 1-4	July 11	N.D. [$<5.0 \times 10^{-1}$]	N.D. [$<5.3 \times 10^{-1}$]

[]:detection limit

4. Evaluation:
Pu-238,Pu-239 and Pu-240 were not detected from the samples.