

携行品汚染発生状況報告(平成28年3月)

場所: 雑固体廃棄物焼却設備建屋

(単位: 件数)

| 日 | 4Bq/cm ² 以上 40Bq/cm ² 以下 | 40Bq/cm ² 超過 | 汚染発生合計 | 除染措置 | |
|----|---|-------------------------|--------|------|------|
| | | | | 持出可 | 持出不可 |
| 1 | 0 | 0 | 0 | 0 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 |
| 8 | 0 | 0 | 0 | 0 | 0 |
| 9 | 1 | 0 | 1 | 0 | 1 |
| 10 | 1 | 0 | 1 | 0 | 1 |
| 11 | 2 | 0 | 2 | 0 | 2 |
| 12 | 0 | 0 | 0 | 0 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 |
| 14 | 1 | 0 | 1 | 0 | 1 |
| 15 | 2 | 0 | 2 | 0 | 2 |
| 16 | 3 | 0 | 3 | 0 | 3 |
| 17 | 1 | 0 | 1 | 0 | 1 |
| 18 | 2 | 0 | 2 | 0 | 2 |
| 19 | 0 | 0 | 0 | 0 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 |
| 21 | 0 | 0 | 0 | 0 | 0 |
| 22 | 0 | 0 | 0 | 0 | 0 |
| 23 | 0 | 0 | 0 | 0 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 |
| 30 | 1 | 0 | 1 | 0 | 1 |
| 31 | 0 | 0 | 0 | 0 | 0 |
| 合計 | 14 | 0 | 14 | 0 | 14 |