

# 車両汚染部位記録シート(2019年7月)

(単位:台数)

日	測定台数	13kcpm以上	除染後 退構可車	除染後 退構不可車	除染対象外 退構不可車
1	211	0	0	0	0
2	223	0	0	0	0
3	251	0	0	0	0
4	210	0	0	0	0
5	303	0	0	0	0
6	78	0	0	0	0
7	30	0	0	0	0
8	224	1	1	0	0
9	246	0	0	0	0
10	233	0	0	0	0
11	257	1	0	0	1
12	240	0	0	0	0
13	53	0	0	0	0
14	16	0	0	0	0
15	67	0	0	0	0
16	280	0	0	0	0
17	254	1	1	0	0
18	255	0	0	0	0
19	247	0	0	0	0
20	61	0	0	0	0
21	15	0	0	0	0
22	212	0	0	0	0
23	206	0	0	0	0
24	247	0	0	0	0
25	231	0	0	0	0
26	241	2	2	0	0
27	52	0	0	0	0
28	15	0	0	0	0
29	219	0	0	0	0
30	244	1	1	0	0
31	218	1	0	0	1
合計	5639	7	5	0	2