

# 身体汚染発生状況報告(2021年9月)

場所:事務本館 汚染検査所

|     |               |
|-----|---------------|
| 作成日 | 2021年10月1日(金) |
| 作成者 |               |
| 審査者 |               |
| 承認者 |               |

(単位:件数)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 1    | 1    | 2    | 0     | 0     |
| 2  | 0    | 1    | 0    | 0     | 0     |
| 3  | 0    | 0    | 2    | 0     | 0     |
| 4  | 0    | 0    | 1    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 2    | 0    | 2    | 2     | 0     |
| 7  | 3    | 0    | 0    | 0     | 0     |
| 8  | 4    | 1    | 1    | 2     | 0     |
| 9  | 1    | 1    | 3    | 1     | 0     |
| 10 | 1    | 2    | 4    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 3    | 1    | 1    | 1     | 0     |
| 14 | 0    | 0    | 2    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 1     | 0     |
| 17 | 3    | 0    | 1    | 2     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 1     | 0     |
| 22 | 1    | 1    | 1    | 1     | 0     |
| 23 | 1    | 1    | 0    | 0     | 0     |
| 24 | 0    | 0    | 2    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 1    | 0    | 0    | 0     | 0     |
| 28 | 1    | 0    | 2    | 2     | 0     |
| 29 | 2    | 0    | 1    | 0     | 0     |
| 30 | 3    | 0    | 0    | 0     | 0     |
|    |      |      |      |       |       |
| 合計 | 27   | 9    | 25   | 13    | 0     |

基準値:4[Bq/cm<sup>2</sup>]以下

# 身体汚染発生状況報告(2021年9月)

|     |          |
|-----|----------|
| 作成日 | 10月1日(金) |
| 作成者 |          |
| 審査者 |          |
| 承認者 |          |

場所:入退域管理施設

(単位:件)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 1     | 1     |
| 2  | 0    | 0    | 0    | 1     | 0     |
| 3  | 0    | 0    | 0    | 1     | 0     |
| 4  | 0    | 1    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 1    | 1    | 0     | 0     |
| 7  | 0    | 0    | 0    | 1     | 0     |
| 8  | 1    | 1    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 1     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 1    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 2     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 1    | 0    | 2     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 1    | 0    | 0    | 1     | 0     |
| 22 | 0    | 2    | 0    | 3     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 1     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 1     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
| 合計 | 3    | 6    | 1    | 14    | 2     |

基準値:4[Bq/cm<sup>2</sup>以下]

# 身体汚染発生状況報告(2021年9月)

場所: 免震重要棟 2階 チェックポイント

|     |               |
|-----|---------------|
| 作成日 | 2021年10月1日(金) |
| 作成者 |               |
| 審査者 |               |
| 承認者 |               |

(単位: 件数)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 1     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 0    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
| 合計 | 0    | 0    | 0    | 1     | 0     |

基準値: 4[Bq/cm<sup>2</sup>] 以下

# 身体汚染発生状況報告(2021年9月)

場所: 免震重要棟休憩所 第二工区

|     |               |
|-----|---------------|
| 作成日 | 2021年10月1日(金) |
| 作成者 |               |
| 審査者 |               |
| 承認者 |               |

(単位: 件数)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 1    | 0    | 0     | 0     |
| 7  | 0    | 0    | 1    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 1    | 0    | 0     | 0     |
| 17 | 0    | 0    | 0    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
|    |      |      |      |       |       |
| 合計 | 0    | 2    | 1    | 0     | 0     |

基準値: 4[Bq/cm<sup>2</sup>] 以下

# 身体汚染発生状況報告(2021年9月)

場所: 1/2号機 サービス建屋(1F) 休憩所

|     |               |
|-----|---------------|
| 作成日 | 2021年10月1日(金) |
| 作成者 |               |
| 審査者 |               |
| 承認者 |               |

(単位: 件数)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 0    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
|    |      |      |      |       |       |
| 合計 | 0    | 0    | 0    | 0     | 0     |

基準値: 4[Bq/cm<sup>2</sup>] 以下

# 身体汚染発生状況報告(2021年9月)

場所: 1/2号機 サービス建屋(1F) 装備交換所

|     |               |
|-----|---------------|
| 作成日 | 2021年10月1日(金) |
| 作成者 |               |
| 審査者 |               |
| 承認者 |               |

(単位: 件数)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 0    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
|    |      |      |      |       |       |
| 合計 | 0    | 0    | 0    | 0     | 0     |

基準値: 4[Bq/cm<sup>2</sup>] 以下

# 身体汚染発生状況報告(2021年9月)

場所: 1/2号機 サービス建屋(2F) 休憩所

|     |               |
|-----|---------------|
| 作成日 | 2021年10月1日(金) |
| 作成者 |               |
| 審査者 |               |
| 承認者 |               |

(単位: 件数)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 0    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
|    |      |      |      |       |       |
| 合計 | 0    | 0    | 0    | 0     | 0     |

基準値: 4[Bq/cm<sup>2</sup>] 以下

# 身体汚染発生状況報告(2021年9月)

場所: 3/4号機 サービス建屋(2F) 休憩所

|     |               |
|-----|---------------|
| 作成日 | 2021年10月1日(金) |
| 作成者 |               |
| 審査者 |               |
| 承認者 |               |

(単位: 件数)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 0    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 1    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
|    |      |      |      |       |       |
| 合計 | 0    | 1    | 0    | 0     | 0     |

基準値: 4[Bq/cm<sup>2</sup>] 以下

# 身体汚染発生状況報告(2021年9月)

|     |            |
|-----|------------|
| 作成日 | 9月 30日 (木) |
| 作成者 |            |
| 審査者 |            |
| 承認者 |            |

場所: 5/6号機サービス建屋休憩所

(単位:件数)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 1     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 2     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 1     | 0     |
| 14 | 0    | 0    | 0    | 2     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 1     | 0     |
| 17 | 0    | 0    | 0    | 4     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 1     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 2     | 0     |
| 合計 | 0    | 0    | 0    | 14    | 0     |

基準値:4[Bq/cm<sup>2</sup>]以下

# 身体汚染発生状況報告(2021年9月)

|     |            |
|-----|------------|
| 作成日 | 9月 30日 (木) |
| 作成者 |            |
| 審査者 |            |
| 承認者 |            |

場所: 企業センター厚生棟休憩所

(単位:件数)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 0    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
| 合計 | 0    | 0    | 0    | 0     | 0     |

基準値:4[Bq/cm<sup>2</sup>]以下

# 身体汚染発生状況報告(2021年9月)

|     |            |
|-----|------------|
| 作成日 | 9月 30日 (木) |
| 作成者 |            |
| 審査者 |            |
| 承認者 |            |

場所: 企業センターA棟休憩所

(単位:件数)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 1    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 1    | 1    | 1     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 1     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 1    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 1    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 1    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 1     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 1     | 0     |
| 合計 | 0    | 2    | 4    | 4     | 0     |

基準値:4[Bq/cm<sup>2</sup>]以下

# 身体汚染発生状況報告(2021年9月)

場所:登録センター休憩所

(単位:件)

|     |          |
|-----|----------|
| 作成日 | 10月1日(金) |
| 作成者 |          |
| 審査者 |          |
| 承認者 |          |

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 1    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 1    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
|    |      |      |      |       |       |
| 合計 | 0    | 0    | 2    | 0     | 0     |

基準値:4[Bq/cm<sup>2</sup>]以下

# 身体汚染発生状況報告(2021年9月)

|     |          |
|-----|----------|
| 作成日 | 10月1日(金) |
| 作成者 |          |
| 審査者 |          |
| 承認者 |          |

場所: 雑固体廃棄物焼却設備建屋(管理区域)

(単位: 件)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 0    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
| 合計 | 0    | 0    | 0    | 0     | 0     |

基準値: 4[Bq/cm<sup>2</sup>以下]

# 身体汚染発生状況報告(2021年9月)

|     |          |
|-----|----------|
| 作成日 | 10月1日(金) |
| 作成者 |          |
| 審査者 |          |
| 承認者 |          |

場所: 雑固体廃棄物焼却設備建屋(管理対象区域)

(単位: 件)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 1    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 0    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
| 合計 | 0    | 0    | 1    | 0     | 0     |

基準値: 4[Bq/cm<sup>2</sup>以下]

# 身体汚染発生状況報告(2021年9月)

|     |          |
|-----|----------|
| 作成日 | 10月1日(金) |
| 作成者 |          |
| 審査者 |          |
| 承認者 |          |

場所:増設雑固体廃棄物焼却設備建屋(管理対象区域)

(単位:件)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 0    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
| 合計 | 0    | 0    | 0    | 0     | 0     |

基準値:4[Bq/cm<sup>2</sup>以下]

# 身体汚染発生状況報告(2021年9月)

|     |          |
|-----|----------|
| 作成日 | 10月1日(金) |
| 作成者 |          |
| 審査者 |          |
| 承認者 |          |

場所:土捨て場休憩所

(単位:件)

| 日  | 身体汚染 | 下着汚染 | 靴下汚染 | 一般服汚染 | 装備品汚染 |
|----|------|------|------|-------|-------|
| 1  | 0    | 0    | 0    | 0     | 0     |
| 2  | 0    | 0    | 0    | 0     | 0     |
| 3  | 0    | 0    | 0    | 0     | 0     |
| 4  | 0    | 0    | 0    | 0     | 0     |
| 5  | 0    | 0    | 0    | 0     | 0     |
| 6  | 0    | 0    | 0    | 0     | 0     |
| 7  | 0    | 0    | 0    | 0     | 0     |
| 8  | 0    | 0    | 0    | 0     | 0     |
| 9  | 0    | 0    | 0    | 0     | 0     |
| 10 | 0    | 0    | 0    | 0     | 0     |
| 11 | 0    | 0    | 0    | 0     | 0     |
| 12 | 0    | 0    | 0    | 0     | 0     |
| 13 | 0    | 0    | 0    | 0     | 0     |
| 14 | 0    | 0    | 0    | 0     | 0     |
| 15 | 0    | 0    | 0    | 0     | 0     |
| 16 | 0    | 0    | 0    | 0     | 0     |
| 17 | 0    | 0    | 0    | 0     | 0     |
| 18 | 0    | 0    | 0    | 0     | 0     |
| 19 | 0    | 0    | 0    | 0     | 0     |
| 20 | 0    | 0    | 0    | 0     | 0     |
| 21 | 0    | 0    | 0    | 0     | 0     |
| 22 | 0    | 0    | 0    | 0     | 0     |
| 23 | 0    | 0    | 0    | 0     | 0     |
| 24 | 0    | 0    | 0    | 0     | 0     |
| 25 | 0    | 0    | 0    | 0     | 0     |
| 26 | 0    | 0    | 0    | 0     | 0     |
| 27 | 0    | 0    | 0    | 0     | 0     |
| 28 | 0    | 0    | 0    | 0     | 0     |
| 29 | 0    | 0    | 0    | 0     | 0     |
| 30 | 0    | 0    | 0    | 0     | 0     |
|    |      |      |      |       |       |
| 合計 | 0    | 0    | 0    | 0     | 0     |

基準値:4[Bq/cm<sup>2</sup>]以下