

身体汚染発生状況報告(2022年8月)

作成日	9月1日(木)
作成者	
審査者	
承認者	

場所: 雑固体廃棄物焼却設備建屋(管理区域)

(単位: 件)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

基準値: 4[Bq/cm<sup>2</sup>以下]

身体汚染発生状況報告(2022年8月)

作成日	9月1日(木)
作成者	
審査者	
承認者	

場所: 雑固体廃棄物焼却設備建屋(管理対象区域)

(単位: 件)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

基準値: 4[Bq/cm<sup>2</sup>以下]

身体汚染発生状況報告(2022年8月)

作成日	9月1日(木)
作成者	
審査者	
承認者	

場所: 増設雑固体廃棄物焼却設備建屋(管理対象区域)

(単位: 件)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

基準値: 4[Bq/cm<sup>2</sup>以下]

携行品汚染発生状況報告(2022年8月)

作成日	9月1日(木)
作成者	
審査者	
承認者	

場所: 雑固体廃棄物焼却設備建屋(管理区域)

(単位: 件)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				搬出可	搬出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

携行品汚染発生状況報告(2022年8月)

作成日	9月1日(木)
作成者	
審査者	
承認者	

場所: 雑固体廃棄物焼却設備建屋(管理対象区域)

(単位: 件)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				搬出可	搬出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

携行品汚染発生状況報告(2022年8月)

作成日	9月1日(木)
作成者	
審査者	
承認者	

場所: 増設雑固体廃棄物焼却設備建屋(管理対象区域)

(単位: 件)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				搬出可	搬出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	1	0	1	0	1
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	1	0	1	0	1