

Sampling Results Regarding the Influence on the Water Leak at a Tank in the H4 area in Fukushima Daiichi Nuclear Power Station

Unit: Bq/L

	Groundwater around H4 area				
	E-1	E-2	E-3	E-4	E-5
Date of Sampling		Sep 5, 2013			
Time of sampling		10:50 AM			
All β		330			
H-3 (Approx. 12 years)		Under analysis			

