

## Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

### <Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND ( 6.8E-01 )	ND ( 6.4E-01 )	Treated water tank	Aug 29, 2014	4:10 PM
Cs-137	ND ( 6.3E-01 )	ND ( 7.4E-01 )			
Gross β	ND ( 4.0E+00 )	ND ( 4.5E+00 )			
Tritium	1.8E+02	1.1E+02	Receiving tank	Aug 27, 2014	2:50 PM
Notification density rate*	0.15	0.17			

\* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

\* Analysis of tritium is performed at Environment Management Building.