

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (5.6E-01)	ND (6.7E-01)	Treated water tank	Nov 12, 2014	4:20 PM
Cs-137	ND (5.8E-01)	ND (8.8E-01)			
Gross β	ND (4.0E+00)	ND (4.3E+00)			
Tritium	1.7E+02	1.6E+02	Receiving tank	Nov 10, 2014	1:20 PM
Notification density rate*	0.15	0.17			

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.