

Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

<Mobile RO membrane system>

	Measurement result [Bq/L]		Sampling place	Sampling date	Sampling time
	Chemical Analysis Building *	Laboratory at Unit 5 and 6			
Cs-134	ND (6.5E-01)	ND (8.5E-01)	Treated water tank	Nov 19, 2014	4:15 PM
Cs-137	ND (6.0E-01)	ND (7.8E-01)			
Gross β	ND (8.0E-01)	ND (1.4E+00)			
Tritium	1.7E+02	1.6E+02	Receiving tank	Nov 14, 2014	3:10 PM
Notification density rate*	0.047	0.072			

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* Analysis of tritium is performed at Environment Management Building.