

# A Foreign Material Found in Unit 6 Spent Fuel Pool at Fukushima Daiichi NPS

<Reference>


May 23, 2013

Tokyo Electric Power Company

- Since May 20, 2013, inspection of the spent fuel rack installed in Unit 6 spent fuel pool has been started.
- Around 3:10 PM on May 23, a TEPCO employee, who was checking a video recording inspection of the spent fuel rack, found a foreign material (something like an eye nut) at the bottom of the east side of Unit 6 spent fuel pool.



<Condition of the foreign material>  
Photo taken on May 23, 2013



<Overhead image of the spent fuel pool>