

(Reference) Investigation of the PCV interior of Unit 2

A1. Investigation of the condition of the CRD rail (conducted in August, 2013)

A2. Investigation of the condition of the Platform inside the Pedestal

A3. Investigation of the condition of the lower part of the CRD and the Platform

A4. Investigation of the condition on the underground floor of the Pedestal

What has to be done in order to use the X-6 penetration pipe

- Remove the blocks in front of the pipe (completed)
- Decontamination in front of the pipe (in progress)
- Bore a hole in the hatch of the penetration pipe
- Remove objects inside the penetration pipe

