


Measurement Results of Dose Rate at Unit 2 Reactor Building of Fukushima Daiichi (conducted on July 8)

July 11, 2011
Tokyo Electric Power Company

Migration path of robot
Camera's direction



Layout of buildings are image figures (scale size and layout are not reflected correctly)