


Place where high radiation dose was detected
on the 2nd floor of Turbine Building, Unit 1, at Fukushima Daiichi Nuclear Power Station



Place: Near the entrance of the train room for emergency gas treatment system, 2nd floor of Turbine Building, Unit 1

Time: At around 11:19 am, on August 2, 2011

Photo by : Tokyo Electric Power Company

Train room for emergency gas treatment system