


Debris removal works with heavy machinery at Fukushima Daiichi Nuclear Power

< target area >



< Results >

- Term : 4/10 ~ 11/17
- Area : approx. 56,000 m²
- Amount : approx. 20,000 m³
outdoors only (indoors excluded)

former main building entrance

< Before >



May 27, 2011



< After >



June 7, 2011

the road between unit 2 & unit 3

< Before >



May 3, 2011



< After >



May 14, 2011

Other photos are published on the report "Roadmap towards Restoration from the Accident at Fukushima Daiichi Nuclear Power Station (November 17, 2011)"