

【Reference】

Situation of Water Leakage at First Floor in Reactor Building at Unit 4 of Fukushima Daiichi Nuclear Power Station

February 2, 2012

Tokyo Electric Power Company

<Image of first floor in Reactor building at Unit 4 of Fukushima Daiichi Nuclear Power Station

■Date and Time

Around 3:20 pm February 2, 2012

■Detector


Tepeco worker

■Place of Leakage

Nearby north west corner at first floor in reactor building at unit 4 of Fukushima Daiichi Nuclear Power Station

■Leaked Water

filtrate water



Date : February 2, 2012

Photo : Tokyo Electric Power Company