Result of the Sampling regarding the Water Leakage in the Transfer Pipes from Water Desalinations (Reverse Osmosis Membrane) to Concentrated Water Storage Tanks of in Fukushima Daiichi Nuclear Power Station

Sampling Results on the Point around the South Discharge Canal of Unit 1-4

【Sampling Point】 Point around the Discharge Canal of Unit 1-4

【Sampling Date and Time】 At 8:30 on April 18, 2012

[Results]

Nuclide	Concentration of Radioactive Material (Bq/cm3)	Limit of Detection (Bq/cm ³)	Half-life Period
I-131	Below Limit of Detection	8 . 0 × 1 0 ⁻⁴	About 8 days
Cs-134	Below Limit of Detection	2 . 1 × 1 0 ⁻³	About 2 years
Cs-137	6 . 0 × 1 0 ⁻³	2 . 5 × 1 0 ⁻³	About 30 years
Sb-125	Below Limit of Detection	2 . 2 × 1 0 ⁻³	About 3 years
All	Below Limit of Detection	2 . 6 × 1 0 ⁻²	-