



Water Leak from the Decontamination Apparatus



ITV (Oscillation and zooming supported)

Photo ,  Area affected by water leak (Depth: 1cm)

 Area affected by water leak (Depth: 0.5cm)

**Dam (The area indicated by a dotted line is a dam)
No leakage detector is installed.**



Monitoring camera image



Monitoring camera image (Enlarged)



Photo taken at the site

Photo taken by TEPCO on June 14, 2012

Overview of Circulating Purification Operation

The sludge in the waste liquid treatment water tank is transferred to the waste liquid receiving tank to be purified.

The acti-flow (the pump is currently out-of-order) functions as a bypass.

The apparatus has been on isolated circulating operation since May 21.

