


Investigation Result of the Water Leak from the Decontamination Apparatus (Occurred on June 14)



Condition of the Waste Liquid Storage Tank

- A trace of water leak was found on the upper lid.
- The discharged water inlet pipe of DAF is inserted into the waste liquid storage tank (Water seems to have overflowed from the gap)
- The water overflowed from the upper lid seems to have flown into DAF (The left area on the photo)





Photo taken by TEPCO on June 15, 2012