


Soot Found in the Power Panel of Unit 5 Instrument Air Compressor at Fukushima Daiichi Nuclear Power Station



Inside the power panel



Electromagnetic contactor



Black soot found

Terminal area of the electromagnetic contactor (Enlarged image)