


Decrease in the Reactor Injection Amounts at Unit 1-3 at Fukushima Daiichi Nuclear Power Station (Follow-up Report)

Buffer Tank Purification

[Outline of the buffer tank purification equipment]



[Substances found during the purification done from September 8 to 10]



September 7: Equipment set-up / trial operation

September 8-10: Purification

Photo taken on September 10, 2012 by TEPCO

Buffer Tank Water Investigation



Buffer tank water



View from the above

Photos taken on September 10, 2012 by TEPCO