

# Investigation of the Inside of Unit 1 PCV Using a CCD Camera at Fukushima Daiichi Nuclear Power Station (October 10)

< Reference >  
October 11, 2012  
Tokyo Electric Power Company

## [Investigation using a CCD camera]

Number of workers involved: 51

Time: From around 10:00 AM to around 1:00 PM



1. Grating



2. Accumulated water (Water surface)



3. Accumulated water (Under water) Photos taken on October 10, 2012 by TEPCO