

Investigation of the Inside of Unit 1 PCV Using a CCD Camera at Fukushima Daiichi Nuclear Power Station (October 11)

< Reference >
October 12, 2012
Tokyo Electric Power Company

[Investigation using a CCD camera]

Number of workers involved: 49

Time: From around 10:00 AM to around 2:00 PM



1. Surface of the jet deflector



2. Floor of the dry well

Photos taken on October 11, 2012 by TEPCO