


Fire Occurred Near Units 1-2 Ultrahigh Voltage Switchyard (Outdoor) at Fukushima Daiichi Nuclear Power Station

[Location where the fire occurred (Aerial photo)]

[Location where the fire occurred (Power station map)]



[Location where the fire occurred (Surrounding area)]



Though the area affected by the fire was initially estimated to be “approx. 20m x approx. 20m”, it was determined to be “approx. 20m x approx. 34m” as a result of a measurement performed afterwards.