

## 4. Operation logs

### Disclaimer

This English translation is only for reference purpose. When there are any discrepancies between original Japanese version and English translation version, the original Japanese version always prevails.

## **Unit 1,2 Shift Supervisor Task Handover Journal**

Form-1

Fukushima Daiichi Nuclear Power Plant Unit 1 and 2

Shift Supervisor Task Handover Journal ( 1/3 )

Shift Supervisor Task Handover Journal

				[confirmed by ] Chief engineer of reactors
March 11, 2011, Friday, 8:30, Shift 2, Group E				[ confirmed by ] Supervisor of next shift
				[ made and approved by ] Shift supervisor
On duty 11 ( operator ) - ( instructor ) 1 ( trainee )	No. of organization	Off duty	[REDACTED]	Support duty
	172	On proxy duty	[REDACTED]	-
Unit 1	Generator Output	460MWe	Reactor Status	[in operation] • start up • hot shutdown • cold shutdown • fuel exchange
Unit 2	Generator Output	789MWe	Reactor Status	[in operation] • start up • hot shutdown • cold shutdown • fuel exchange
Notes				
Unit 1				
1. Operation Status				
(1) Generator output 460MWe in operation				
(2) M.COND B/W 04:04~04:51				
2. Compliance status of safety regulation				
No specific event				
3. Periodic test				
None				
4. Requested work, non compliance event				
None				
5. Status of waste treatment facility				
None				

## Form-1

Fukushima Daiichi Nuclear Power Plant Unit 1 and 2

March 11, 2011, Friday, Shift 2, Shift Supervisor Task Handover Journal ( 2/3 )

Form-1

Fukushima Daiichi Nuclear Power Plant Unit 1 and 2

## Major Test Items

March 11, 2011, Friday, Shift 2, Shift Supervisor Task Handover Journal ( 3/3 )

Test Items		Test Frequency	Unit 1	Unit 2	Notes
1	Core Minimum Fraction of limiting Critical Power ratio (CMFCP)	1/ shift	0.85	0.90	
2	Core Maximum Fraction of Limiting Power Density (CMFLPD)	1/ shift	0.81	0.76	
3	Reactor lowest water level	1/ shift	925mm	1130 mm	
4	Spent fuel pool highest temperature	1/ shift	25 C	26 C	
5	Spent fuel pool water level status	1/ shift	Around overflow water level	Around overflow water level	
6	Reactor coolant maximum temperature change rate	at the time of activation and shutdown—	—C / hr	—C / hr	
7	RPV lowest temperature	At the time of pressure resistance test of RPV	—C	—C	

(Form for Unit 1, 2 and 5,6)

## Form-1

Fukushima Daiichi Nuclear Power Plant Unit 1 and 2

Shift Supervisor Task Handover Journal ( 1/4 )

# Shift Supervisor Task Handover Journal

Form-1

Fukushima Daiichi Nuclear Power Plant Unit 1 and 2

March 11, 2011, Friday, Shift 1, Shift Supervisor Task Handeover Journal ( 2/4 )

(Unit 1)
2. Compliance status of safety regulation
(1) Safety regulation, article 17 (procedures at the time of earthquake and fire)
- report to O&M general manager at the occurrence of earthquake with an intensity of more than lower 5 14:50
(2) Safety regulation, article 76 (basic procedures at the occurrence of abnormal event)
- report to O&M general manager at the occurrence of reactor automatic scram 14:50
(3) Safety regulation, article 77 (procedures at the time of abnormal event)
- operation following "the operation procedures in case of reactor scram" 14:46
(4) Safety regulation, article 113 (report)
- report to O&M general manager at the occurrence of specific event (loss of all A/C power ) stipulated by the act on special measures concerning nuclear emergency preparedness, article 10, clause 1 15:41
- report to O&M general manager at the occurrence of specific event (loss of all coolant water) stipulated by the act on special measures concerning nuclear emergency preparedness, article 15, clause 1 16:36 / report of cancellation 16:45
- report to O&M general manager at the occurrence of specific event ( loss of all coolant water) stipulated by the act on special measures concerning nuclear emergency preparedness, article 15, clause 1 17:07
3. Periodic test
(1) MTb safety facility test Passed 09:42~09:52
(2) Sealed oil system test Passed 09:42~09:52
4. Requested work, non compliance event
None
5. Status of waste treatment facility
None

Form-1

Fukushima Daiichi Nuclear Power Plant Unit 1 and 2

March 11, 2011, Friday, Shift 1, Shift Supervisor Task Handover Journal ( 3/4 )

Unit 2		
1. Operation Status		
(1) Reactor is shutdown		
(2) Alarm "SEISMIC MONITOR TRIP"		14:47
(3) Reactor automatic scram, main turbine automatic shutdown (occurrence of the earthquake)		14:47
(4) Status of reactor "operation" to "hot shutdown"		14:47
(5) Insertion of all control rods		14:47
(6) Reactor mode switch "operation" to "shutdown"		14:47
(7) D/G 2A automatic start up (Okuma-2 line off site power lost) / trip		14:47/15:41
(8) Full opening of MSIV		14:47
(9) M COND Vac break		14:55
(10) Reactor in subcriticality		15:01
(11) RCIC manual start up		15:02
(12) Torus cooling / Torus spray in service		15:07/15:25
(13) RPS MG (A)/(B) restart up		15:27/15:29
(14) D/G 2B breaker trip (running stand-by) / trip		15:40/15:42
(15) M/C2E trip		15:41
(16) Loss of all A/C power		15:41
2. Compliance status of safety regulation		
(1) Safety regulation, article 17 (procedures at the time of earthquake and fire)		
- report to O&M general manager at the occurrence of earthquake with an intensity of more than lower 5		14:50
(2) Safety regulation, article 76 (basic procedures at the occurrence of abnormal event)		
- report to O&M general manager at the occurrence of reactor automatic scram		14:50
(3) Safety regulation, article 77 (procedures at the time of abnormal event)		
- operation following "the operation procedures in case of reactor scram"		14:47
(4) Safety regulation, article 113 (report)		
- report to O&M general manager at the occurrence of specific event ( loss of all A/C power) stipulated by the act on special measures concerning nuclear emergency preparedness, article 10, clause 1		15:41
3. Periodic test		
(1) T-RFP oil tank oil level alarm test, automatic start up test of oil pump	Passed	10:05~10:29
(2) MTb safety device test	Passed	10:33~10:43
(3) Sealed oil system test	Passed	11:06~11:17
4. Requested work, non compliance event		
None		
5. Status of waste treatment facility		
None		
6. Others		
(1) Occurrence of the earthquake		14:46
Intensity of higher 6: Naraha town (Kitada), Tomioka town (Motooka), Okuma town (Shimonogami, Nogami), Futawa Town (Shinzan)		
(2) Alarm warning for huge Tsunami		14:58

Form-1

Fukushima Daiichi Nuclear Power Plant Unit 1 and 2

## Major Test Items

March 11, 2011, Friday, Shift 1, Shift Supervisor Task Handover Journal ( 4/4 )

Test Items		Test Frequency	Unit 1	Unit 2	Notes
1	Core Minimum Fraction of limiting Critical Power ratio (CMFCP)	1/ shift	0.85	0.90	
2	Core Maximum Fraction of Limiting Power Density (CMFLPD)	1/ shift	0.81	0.76	
3	Reactor lowest water level	1/ shift	917 mm	1129 mm	
4	Spent fuel pool highest temperature	1/ shift	25	26	
5	Spent fuel pool water level status	1/ shift	Around overflow water level	Around overflow water level	
6	Reactor coolant maximum temperature change rate	at the time of activation and shutdown—	— / hr	— / hr	
7	RPV lowest temperature	At the time of pressure resistance test of RPV	—	—	

(Form for Unit 1, 2 and 5,6)

# **Unit 1 Operator Task Handover Journal**

### Pattern-2

# Unit 1 Fukushima Daichi Nuclear Power Station

## Operator Task Handover Journal

---

Operator Task Handover Journal( 1 / 2 )

## Pattern-2

## Unit 1 Fukushima Daichi Nuclear Power Station

March 11 2011 ( Shift 2 ) Operator Task Handover Journal( 2 / 2 )

Operation · Time of Event	Time	Context	Classification
	21:05	Main Control Room PNL Alarm Test	
	21:05	[subject to Ministerial Order issue 62]	O
	07:06	MP PNL Alarm Test R/W PNL Alarm Test	
	20:46	RW/B1 Floor RT operation completed (All completed) *FPC F/D Turning Valve inspection	P
	00:05	Generator Voltage Pattern "G1 G0" changed	O
	00:31 / 00:31	Alarm [LP HEATER 2A LEVEL HIGH] 「Occurred」 / 「Clear」	Others
	00:33 ~ 00:37	TCW Hx(A/C) B/W	
	04:43 ~ 04:47	RCW Hx(B/C) B/W	O
	05:53	R PV hydrogen injection amount 「Auto」 「little」 * T/B Operation Floor work (4uHTR demolition)	P
06:33 ~ 06:45 CW Ferrous Flushing			
06:40 ~ 07:30 M. Condenser vacuum tuning 5.5 5.0 kPa E-3A valve opening degree: 6.5 7.0% (5Topen)			
Notes on classification M : MRF issued N : Non compliant report R : Regular Test · Switching O : Operation P : PTW RW:R/W related Mon : Monitoring Others :			
Others			

Pattern-2

## Unit 1 Fukushima Daichi Nuclear Power Station

## Operator Task Handover Journal

Operator Task Handover Journal( 1 / 3 )

March 11, 2011 (Friday)			Shift 1 Group A			[Approval] Shift Advisor				
Name of predecessor (Recorder)										
Name of successor										
Operation Status	Reactor Status	In Operation	Start up	Hot shutdown	Cold shutdown	In fuel exchange				
	Generator output	█	MW	E/M servo	█	%	T	█	MPa	█
	Reactor heat output	█	MW t	R/B pressure difference	█	kPa	R	█	MPa	█
	Core flow rate	█	t/h	Core electro conductivity	█	μS	S	█	MPa	█
	P L R speed master	█	%	Core PH	█		FPC	Inlet electro conductivity	█	μS
	PLR seal pressure	█	MPa	R/B EqD tank level	█	m	FPC	Skimmer level	█	m
	Condenser vacuum rate	█	kPa	FPC Hx(A) Outlet temperature	█		Fuel Pool Upper part	temperature	█	
	S/P water level	█	mm	FPC Hx (B) Outlet temperature	█		Fuel Pool Bottom part	temperature	█	
	CST water level	█	%	Atmospheric pressure	█	hPa	(Extracted Time: : )			
Exception of interlock regarding LCO			None							
Operation status of switching tests	Operated time	Context			Result	Status				
	9:42 ~ 9:52	Thrust abrasion detector operation test			Pass	Fine · caution · in progress · cancelled				
	10:37 ~ 10:50	Emergency seal oil pump automatic startup test			Pass	Fine · caution · in progress · cancelled				
		Ultra high voltage switching yard insulator wash			-	Fine · caution · in progress · cancelled				
		Injection of ferrous sulfate			-	Fine · caution · in progress · cancelled				
		Main Condenser back wash			-	Fine · caution · in progress · cancelled				
Note										

Pattern-2

## Unit 1 Fukushima Daichi Nuclear Power Station

## March 11 2001 Friday( Shift 1 ) Operator Task Handover Journal( 2 / 3 )

Operation · Time of Event	Time	Context	Classification
	8 : 35	Main Control Room P N L Alarm Test [subject to Ministerial Order issue 62]	
	8 : 36	MP PNL Alarm Test H/U P N L Alarm Test R/W P N L Alarm Test	O
	8 : 56 ~	New Fuel Inspection work	P
	8 : 58 ~	Works to electrify T/B carry-in gate for large stuff	P
	8 : 59	Alarm 「LP HEATER 2A LEVEL HIGH」 / immediately cleared	Others
	9 : 06 ~	Monthly Air conditioner inspection(H/U exhaust fan)	P
	9 : 10	Reactor water sampling manually analyzed figure (9:10) 0.107 µS/cm pH:6.8 * As hydrogen injection is "little", figure rose due to chrome discharge	
	9 : 11 ~ 9 : 35	Taprogge Ball collection & setting TOTAL:95.4% No garbage/shells A:48 (97.0%) B:61 (98.3%) C:137 (92.6%) D:114 (93.9%)	Others
	9 : 14 ~	CUW non generative Hx outlet electro conductivity gauge (SP-14) constant temperature unit inspection	P
	9 : 24 ~ 11 : 13	Exchange of feed water/condensing sampling line metal filter	Others
	9 : 34 ~	Surrounding radioactivity monitoring system transmission line multiplexing work Missing data time(MP-6) HI side:9:58-10:05 LO side:10:17-10:23	P
	9 : 55 ~	L P R M plateau measurement 10:03/10:28 APRM ch1, 5 BY-PS/release 10:28/10:53 " ch2,6 " 11:03/ " ch3, 4 "	P
	9 : 56 ~ 10 : 15	One generator hydrogen cylinder supplied 0.3080 0.317MPa	O
	10 : 08 ~ 10 : 55	OG sampling (Regular sampling) * Vial sample vacuum pump T/R was also implemented Fine	Others
	10 : 10 ~ 11 : 04	PLR M-G(B) brush inspection	P
	10 : 51	Sealed oil Vac pump (B) 密封油Vacポンプ(B) without drain(2 measures)	O
	11 : 13	TCW Hx (A,C) B/W	O
Notes on classification	M : MRF issued N : Non compliant report R : Regular Test · Switching O : Operation P : PTW RW:R/W related Mon : Monitoring Others		

## Pattern-2

Unit 1 Fukushima Daichi Nuclear Power Station

March 11 2001 Friday( Shift 1 ) Operator Task Handover Journal( 3 / 3 )

Pattern-2

Fukushima Daiichi Nuclear Power  
 Station Unit1


March 11 2011 ( Shift 1 ) Operator Task Handover Journal( 1 / )

**Unit 1**


After the earthquake, scrum operation record has been copied from the Main Control Room White Board memo.


Refer to "post earthquake shift task handover memo" after SBO.

Time	Context	Classification
14:46	Occurrence of earthquake <u>Auto scrum succeeded.</u> · D/G 1A·B auto startup · MSIV all auto open - No power · Minimum reactor water level 150mm	Operation • Time of Event
14:46		
14:58	Large Tsunami Alarm announced high tide 20:09 <u>M. Cond vacuum destroyed</u>	
15:06	Fresh water tank flange part (3 arms) leakage confirmed	
15:07	Torus cleaning(A) in service	
15:10	Torus cleaning(B) in service	
15:16	Reactor pressure 6.8MPa Reactor water level +910mm · Rx water level, pressure is controlled at I.C	
15:29 / 15:36	MP-3 Hi-Hi Alarm/ clear (MP 7 reset impossible)	
15:37	D/G1B trip <u>SBO</u> ( <a href="#">When did system A trip?</a> )	
15:50	<u>Power for measurement out</u> water level not known	
17:30	Diesel powered FP startup (due to low pressure alert reset)	
17:47	Diesel powered FP Fuel 272L	
20:50	Diesel powered FP startup	
17:37	T/B BFL about 20cm from the floor	
17:47	Unit 1-2 switching yard not usable (due to breaker omission) * from Emergency response room	
18:18	IIC MO-2A, 3A opened (steam confirmed)	
18:25	IIC MO- 3A closed	
21:30	IC MO- 3A opened (steam confirmed)	
21:16	Original valve of filtration water been open?	
21:21	Fuel range water gauge (A) switched to temporary power +30cm	
21:51	Unit 1 R/B prohibited to enter	
	< After, until 12 March >	
06:14 ~ 06:20	Temporary extinguishing pump preparing for injection (ATOX)	
06:20	Temporary extinguishing pump injection started 1m3	
10:16 ~ 10:25	PCV vent AO-1601-90 open operation Fail	
Notes on classification	M : MRF issued N : Non compliant report R : Regular Test · Switching O : Operation P : PTW RW:R/W related Mon : Monitoring Others : Others	









鳥  
類  
調  
査

MSV	2300	126
松の木下・南	0.5	0.3
" 北	1.2	0.8

0.45?  
3.10?

19091 319 8762mm

29091 427

Perch 38

121-701

172H

1.03

CA1130

350

14 TBS 50<3.

15' 50' : 汽油電源箱水 152.700

15' 53' 電源箱.

16' 41' 水 152.700 - 90cm 電油 152.0

電源

M/C 水 152. N/C 電油 152.0

電源

④ DDTFP - ラ=7.35.7.7.3

電源

7/8 地下全水没. (152.0)

↑ (1) 下水道水 (2) 木外水 (3) 木外水

X  
RCOC

CWPP (1) 水 152.  
(2) 水 152.0

CWP (2) 水 152.0

16' 55' 38.11.0

17' 58' (6' 59') M/C 152.0  
水 152.0 不明 (-150cm) 152.0  
17' 59' 152.0 不明

17' 59' 152.0 (152.0) 152.0

17' 59' 152.0 不明 (152.0) 152.0

17' 59' 152.0 不明 152.0 不明 152.0

15

17'27" 水深. 17'40" 水深 高度 6.32.  
17'35"

15'50' 27 濟電源箱 水位不明

S/B AD 32. 電水. 17 底面取高 162.0

RCOC 管井水.

15' 92' 原始法第10章 管合.

15' 58' トラスカニア H: 14. ANN(通)

16' 03' ANN NSSS 未達

16' 20' EOP ③ STOP

16' 20' 壓力 152.0


23'09' 可: ✓ M/C 水 152.

16' 36' 原始法 15章 管合

17' 16' ECC (N) 溝入水

17'31' ESS 152.0  
水 152.0 不  
通

152.0 水管視測  
XPF  
スラグ + 2 = 7  
ECC  
152.0 水



3  
 17°49' D/FP 燃料 272L → 韓油 E/FI 捕集不可  
 (へいき)  
 17°49' 雨内所 LPG 器體浮 1.20 雨内所 使用不可.  
 (雨内所)  
 17°50' I.C 組換取 検討機器上昇のため. 300CPM  
 17°51' 組合せ S. 新福島ヨクジ有. / 1.20 雨内所使用不可.  
 17°52' 雨内所 M-3 レンジ - 1 台目.

18°00' I.C(2) 系. 2A.3A 同 / 三次先生確認

18°05' " 3A 同

18°39' 10T/8 大物搬入 D. 1m 位水位にて. 垂直壁側に於て壁面破損

18°42' PGS 使用不可.

18°55' 大津港整備完了 → 20°09' 満潮  
19°22' 高圧圧縮. → 2SA 発電機起動中.

設置好 15% (m 位水上昇 盆内も同水)


M/c A.B.C.D.

P/C A.B

P/C C.D (M 位)

DC 電同様 125V

20°40' D/PFP



23 T TO 522S T TO 2011 時刻.  
 17:30' 10:45 時刻 1. 捕集器 S.A. 係  
 9本 T-773- ② ③ 東北電力 發電機 → 壊壊 (E-  
 17:45' 1.20 時刻 0:00'  
 17:50' D/FP 起動後 → I.C(2) 減圧.  
 T.C 5:00' Rx 33: ✓  
 17:53' 3133 2:00' P/C

18°00' 1. 新福島側 E 壁板 1.2 cm 破壊へ

18°12' 23+位監視不可.

14 1.2 cm 3382  
 25A 23 1.2 cm  
 1.2 cm 有.

-1B P/G 篮

-1A P/G 篮 1m 5cm 1.2 cm 有.

20°03' ③ E

SRV 由/由抱器  
0.4kg 7.0 MPa PI60A

0.4kg -140 cm<sup>2</sup> DSN

0.4kg 30KPa

23 M/c 2A 2B 2C 2D 25B

FL P/ 2 cm

L-120 FL M(c-B-2  
M(c 2c-2)

0°20' 機械操作

+40cm

20°40' ⑨ PC CS 駆し. 起點なし

20°50' ⑨ G A 駆動

21°08' 屋外 駆き動作 (2) 23, 音 / 3423  
- 21°n 駆き動作?

現場  
操作

26. 8-27 使用不可 (10m - 0.8m)

21°51' 15 BB 入土域 禁止

1000 CPS

21°11' 水位計 OS 確認. ⑨ +40 cm

A. 7/11. OS

21°13' +30 cm +50 cm

21°16' 埋込元年 16

21°21' 建物城北位置の水位計 +30 cm +40

IC (II) 動作

(B) 水位計 OS 1000 CPS

21°32' +30 cm +50 cm

+45 cm

IC

21°33' IC 3A (II)

21:57 ⑨ +55 cm

22:12 " 59 "

22:16 ⑨ (2a) → H125 B. F. 02913

(総量計 +5.203)

22:16

● ● ● (2) 10-27 A 200

22:22 MP 7 TD 45 7

" 8 TD 45 7

16  
39  
45

10 20  
10 4  
25 25


25 10 4

41

7/2(土)  
4:15' 中擇入口付近 0.65mSV/H + KURE HAB FP? - 雨混  
D/N 倍率 (4人/組 x 2) 10,000

4:30' 現場作業禁止、津波、警戒待合。

4:20~5:00' RCLC DA込み切替 CSE → S6.  
6:14~  
6:20' 消火ボンプ注入準備(●, ●, ●)  
1m3注入開始~




6:22~6:29" 1000ℓ — Reviv (A130 & 35°)

(DYN) 0.75 MPa.

9:04' ~ 9:15' ① 20m/s 25m/s S/C 北西~チャートウ~7~南東 外  
9:24' ~ 9:32' ② 8.9 9.5 R/B 2FL SHCH Hx 室上部  
— ③

10:16' PCV 倍率 + AD-1601-90°雨操作 X  
10:24' " " X  
10:24' " " X



PCV 倍率 AD-1601-90°雨操作

雨操作

1U

$$343 \text{ 脱壳} \\ (V-1) = 4 \times 10^0$$

電動アブレット

3U D/D FP RUNφ

13 3-2 TIE 全角

FP 電動脱壳 0.17 MR. I<sub>PP</sub>

AM ラインより注入 2-端子端子

2U RHRSN. DGSW 動作時間 (V-1) - 3.4ms (設定期間)  
13 12VDC D-5718 (138524h, λ=370s)

DIN A0-90 用/用電源 ST-BY

1.277.21 煙管脱壳

13 12VDC 1A 32VDC 2A 17VDC

④ CT IPP は吸収 2.85V AM ライン (PP41115)

電動アブレットの動作時間 (V-1) - 16.27s  
脱壳時間 (V-1) - 10.4s  
合計時間 (V-1) - 26.67s

脱壳 (V-1) と合算して脱壳時間

脱壳時間 (V-1) + 吸收時間 (V-1) = 26.67s

15 分換算時間 (UA 時間) を加えた結果が  
脱壳時間

2U

Ref C 2 定水頭?

432. 3600m -> 7


CRD (A) SRK (RPM) )  
脱壳時間

④ RCWE = 3.025s (3.3設定期間)  
CROSSD RUN TIME (V-1)

→ 2.7s

IV ~ 50  
0% ~ 100%

$$(1.145-1) = 4 \times 10^0 \\ = 3.725 \text{ kg}$$



14' ● ● ● ● ●

1°05' [津波警報発令中]

2°12'

1°30'

FP

2° HTR室 1°53' - ● ● ●  
水位計 2°10'

4° RCIC入力終了 ST → SC

● ● ● ● ● ● ● ●

4°3' ● ● ● ●

2°10' ● ● ● ● 2°RCIC.

2°15' 0.84 MPa → 0.74 MPa  
(740 kPa.)

850 kPa  
740 kPa

2°25' 0.84 MPa - S/P圧力

3°15' 危急指示: 津波 侵襲警戒

0.85  
0.26  
±6.0

3°30' 3号 FP起動

4°3' 中性放射線上昇 0.18 → 0.33 us/h

6°00' 0.74 MPa

## **Unit 2 Operator Task Handover Journal**

Fukushima Daiichi Nuclear Power Station Unit 2

## Operator Task Handover Journal

Operator Task Handover Journal ( 1 / 3 )

March 11, 2011 Friday				Shift 2 Group E				[Approval] Superviso r		
Name of predecessor (Recorder)				[REDACTED] ( E Group )						
Name of successor				Substitute shift [REDACTED] ( A Group )						
Operation Status	Reactor Status		In Operation	Start up	Hot shutdown	Cold shutdown	In fuel exchange			
	HT-BLNC	2378.8 MWt	R C W	pressure/temperatur	0.56 MPa / 18.9	F P C	Skimmer level	2.5 m	pool temperat	26
	HT-BLNC	99.9 %	P'p B/C Hx B/C			pump&Hx	A F/D A	electro conductivity	0.95 $\mu$ S/cm	
	Generator output	788.8 MWe	SURG LVL	695 mm	GEN H <sub>2</sub> pressure	0.4121 MPa				
	P L R speed A/B	81.2 / 81.4 %	T C W	pressure/temperatur	0.59 MPa / 24.4	S/P level	-21 mm	temperature	15.5	
	Core flow rate	29233 T/H	P'p B/C Hx B/C		atmospheric	p1010.7 hPa	D/W press	5.9 kPa		
	Reactor water temperature	273.9	SURG LVL	1615 mm	M/CON VAC	4.59 kPa.abs				
	Core electro conductivity	0.06 $\mu$ S/cm	S W	pressure/temperatur	0.51 MPa / 7.1	R/B pressure difference	- 0.12 kPa			
CST level	67 %	P'p A/B		(Extracted time: 7 時 20 分)						
Exception of interlock regarding LCO		None								
Operation status of switching Regular tests	Time		Context				Result	Status		
	05 : 02 ~ 05 : 54	M.CON B/W					-	Fine · caution · in progress · cancelled		
備 考										

Fukushima Daiichi Nuclear Power Station Unit 2

March 11, 2011 Friday (Shift 2)

Operator Task Handover Journal ( 2 / 3 )

Operation · Time of Event	Time	Context				Classification
		[subject to Ministerial Order issue 62]				
	21 : 03	Main Control Room P N L Alarm Test				O
	07 : 01	RW P N L Alarm Test				RW
	07 : 05	New FSTR P N L Alarm Test				RW
		[Regular Works]				
	23 : 29 ~ 23 : 31	MOTvapor fan outlet U seal drain extraction	From fill opening	60	120cm	O
	00 : 35 ~ 00 : 39	TCW Hx(B/C) B/W	pressure difference	130	110kPa SW 0.51 0.50MPa	O
	05 : 42 ~ 05 : 46	RCW Hx(B/C) B/W	pressure difference	0.12	0.10MPa SW 0.51 0.51MPa	O
	06 : 53 ~ 07 : 03	Ferrous flushing				O
	04 : 28 / 06 : 07	Alteration of hydrogen injection amount	0.6 0.3ppm / 0.3 0.6ppm			O
	00 : 05	<b>Dispatch order Generator voltage pattern G1 G0</b>				O
	04 : 30	<b>Output Tuning (fall)</b> PLR SPEED 81.5 81.4%				O
		heat output(1minute average) 2380 2379MWt M.COND Vac 4.58kPa.abs				
		SW 7.1				
	06 : 43 ~ 06 : 48	Screen wash pump (C) "Ground 1/4T tightened"	Diffusion	within the range of tray		O
		SWP(A)	"Ground 1/6T tightened"	Diffusion	within the range of tray	
	07 : 00	Storm sample tank received B A switch & B recycle began		1130mm		O
Notes on classification		M:MRF issued	N:Non compliant report	R:Regular Test·Switching	O:Operation	
		P:PTW	RW:R/W related	Mon:Monitoring	Others:Others	

Fukushima Daiichi Nuclear Power Station Unit 2

March 11, 2011 Friday (Shift 2)

Operator Task Handover Journal ( 3 / 3 )

Site Status, Comments to pass on	Context		Classification
	1 . RCW surge tank level was 696mm as of 0:00 (the day before was 703mm) fall rate 0.96 /h (7mm/day) 3/10 RCW sampling implemented.		
	2 . Site status		Mon
	·around T/D(B) HPSV	no haze	
	·around T/D(B) LPSV	no drops / no leaks	
	·T/D leak oil	A: 1drop /10 sec , B: no drop detector450mm	
	·sealed oil W strainer pressure difference	Tb side 11.5kPa / Corrector side 4.6kPa	
	·MO tank vapor fan outlet U seal level	23:31 fill opening 120cm	
	·Bouser filter pump discharge pressure	0.15MPa	
	·Og brackish water seperator outlet hydrogen	0:25 0.160% (hydrogen rated)	
	·R/B Chiller expansion tank level	494mm	
	·H/B drain tank level	6:00 -320mm	
	·Safety release valve after H/B steam header outlet valve[RV-Z2]	1d/1sec leak	
	3 . Time of earthquake		Others
	Subject to the manual, I think we should state the time announced by the Meteorological Agency.		
	Only "Manual for statement of Operator Task Handover Journal"procedures to state Shift Supervisors Task		
	Handover Journal states, <u>Unit 6 seismic instrumentaion data output time</u>		
	so amendment is necessary.		
	Safety Regulation	Article 17 earthquake of surrounding JMA Seismic intensity of over has been monitored ...	
	secondary manual " Manual for management after earthquake		
	·earthquake of surrounding JMA Seismic intensity of 5 over has been monitored ...		
	·earthquakes not subject to safety regulation are managed as maximum earthquake recorded and clas at reference point seismic acceleration		
	After determining that it is over "JMA Seismic intensity of 5" on the flow chart, it is stated to check th maximum figure of reference point seismic acceleration		
	The reference in the manual (document "Report of sesmic status regarding nuclear power plants" writte Manager of Agency for Natural Resource and Energy, public service department, safety audit manager (1991)) states that the time of the <u>occurrence of the earthquake is to be reported.</u>		
	Time of earthquake : The time sesmic wave (P wave) reaches a certain monitoring point (the point is not the fastest arrival point)		
	Response guide after the earthquake (1F version) 7 . Report on earthquake status		
	·Under Chart -3 "Standard of earthquake to be reported", surrounding JMA Seismic intensity or the maximum of the reference point seismic acceleration		
	Secondary manual " Nuclear Power press release manual"		
	·First release surrounding JMA Seismic intensity of over 3		
	·Second release <u>Maximum of the reference point seismic acceleration</u>		
	Due to the fact that the Meteorological Agency data is used for judgements and reports, as well as the documen from Audit Manager, "Earthquake date and time (the Meteorological Agency announcement time)"is considered appropriate for the time of earthquake		
Notes on classification	M:MRF issued P:PTW	N:Non compliant report RW:R/W related	R:Regular Test·Switching Mon:Monitoring Others:Others

Fukushima Daiichi Nuclear Power Station Unit 2

## Operator Task Handover Journal

Operator Task Handover Journal ( 1 / 4 )

March 11, 2011 (Friday)		Shift 1, Group A		[Approval] Shift Supervisor			
Name of predecessor (Recorder)							
Name of successor							
Operation Status	Reactor Status		In Operation	Start up	Hot shutdown	Cold shutdown	In fuel exchange
	HT-BLNC	MWt	R pressure/ temperatur	MPa /	F skimmer level	m pool temperatur	
	HT-BLNC	0.0 %	C P'p	Hx	P pump&Hx	F/D	C conductivity (shift 2) $\mu\text{S}/\text{cm}$
	Generator output	MWe	W SURG LVL	mm	GEN H <sub>2</sub> 压力	MPa	
	P L R speed A/B	/ %	T pressure/ temperatur	MPa /	S/P level	mm	D/W temperature
	Core flow rate	T/H	C P'p	Hx	atmospheric pressure	hPa	press $\mu\text{Pa}$ kPa
	Reactor water temperature		W SURG LVL	mm	M/CON VAC	kPa.abs	
	Core electro conductivity	$\mu\text{S}/\text{cm}$	S pressure/ temperatur	MPa /	R/B pressure difference	-	kPa
CST level	%	W P'p		acted time: : : )			
Exception of interlock regarding LCO							
Operation status of switching regular tests	Time	Context				Result	Status
	10 : 33 ~ 10 : 43	Thrust abrasion test, MTSV test				Passed	Fine
	11 : 06 ~ 11 : 17	Emergency sealed oil (diesel) pump automatic startup test				Passed	Fine
	10 : 13 ~ 10 : 29	RFP-T oil (diesel) pump automatic startuo test				Passed	Fine
	10 : 05 ~ 10 : 12	RFP-T oil (diesel) surface H/L Alarm test				Passed	Fine
	/	ferrous melt / injection start					Fine
	~	M.CON B/W					Fine
	12 : 34	AVR room conditioner switch (A) (B)					Fine
	09 : 02	calculator room conditioner switch (B) (A)					Fine
	09 : 05	Second main control room conditioner switch (B/D) (A/C)					Fine
備 考							

Fukushima Daiichi Nuclear Power Station Unit 2

Operator Task Handover Journal ( 2 / 4 )

Operation · Time of Event	Time	Context	Classification
		[subject to Ministerial Order issue 62]	
08 : 37		Main Control Room P N L Alarm Test	O
		RW P N L Alarm Test	RW
		New FSTR P N L Alarm Test	RW
		[Regular Works]	
10 : 24 ~ 10 : 36		GEN H2 2 supplied 0.411MPa 0.422MPa	
		TCWHx (B/C) B/W	
11 : 49 ~ 11 : 55		RCWHx (B/C) B/W	
		Alteration of hydrogen injection amount 0.6ppm 0.3ppm / 0.3ppm 0.6ppm (M.CO)	
		[Continuing works]	
08 : 40 ~		T/B basement floor coating (ConstructionGr)	
		SPDS server establishing work	
09 : 07 ~ 11 : 46		air conditioner monthly inspection (T/B exhaustFAN)	
09 : 27 ~		RW/B roof coating	
09 : 44 ~		R/B ceiling clane inspection	
09 : 47 ~		Monitoring post inspection (Unit 1PTW)	
		[storm treatment]	
09 : 01 ~ 09 : 10		Storm sample tank B sampling	
12 : 32 ~		Storm sample tank B emission 1130mm 370mm	
08 : 20 / 08 : 20		ANN 「RADWASTE COMMON TROUBLE」 (HVA2-2 TROIBLE) occur / confirmed	
		HVA2-2 TRIP (E-0) RESET and startup. Fine.	
09 : 34 ~ 10 : 45		feed & condensate water metal filter replacement work	
		[TCW Hx A full inspection] ISOL & BLOW	
09 : 31 ~ 09 : 42		TCW Hx A seawater & freshwater seawater : pressure (0.51MPa no change)	
		freshwater : pressure (0.58 0.59MPa)、temperat	
09 : 45		TCW Hx A valve for back wash NFB "OFF" (at centrak position)	
10 : 02		TCW Hx A seawater side blow start two fingers	
10 : 07		TCW Hx A freshwater side blow start two fingers	
09 : 50 ~ 10 : 41		Generator hydrogen gas cylinder 5 cylinders replacement work	
Notes on classification	M: MRF issued N: Non compliant report R: Regular Test·Switching O: Operation P: PTW RW: R/W related Mon: Monitoring Others: Others		

Fukushima Daiichi Nuclear Power Station **Unit 2**

Operator Task Handover Journal ( 3 / 4 )

Fukushima Daiichi Nuclear Power Station Unit 2

Operator Task Handover Journal ( 4 / 4 )


	Context	Classification
1. Site status		
·around T/D(B) HPSV	no haze	
·around T/D(B) LPSV	no drops / no leaks	
·T/D leak oil	A: 1drop/10 seconds , B: no drop detector 450mm	
·sealed oil (diesel) W strainer pressure difference Tb side 10.5kPa / Corrector side 4.5kPa		
·MO tank vapor fan outlet U seal level	10:45 from fill opening 115cm	
·Bouser filter pump discharge pressure	0.15MPa	
·OG brackish water seperator outlet hydrogen	11:20 0.149% (hydrogen rated)	
·R/B Chiller expansion tank level	11:30 493mm	
·H/B drain tank level	10:55 -330mm	
·safety release valve after H/B steam header outlet valve [RV-Z2]	1d/1sec leak	
Site Status · Comments to pass on		
Notes on classification	M: MRF issued P: PTW	N: Non compliant report RW: R/W related
		R: Regular Test · Switching Mon: Monitoring
		O: Operation Others: Others

Fukushima Daiichi Nuclear Power Station **Unit 2**


March 11, 2011 (Friday)


( 1 / 1 )

Operation . Time of Event	Time	Context	Classification
14 : 47		<b>Automatic Scrum "Succeeded"</b> D/G2A,2B Automatic startup , MSIV automatic close (no power)	
14 : 55		Rx level 400mm(MIN)	
15 : 01		M.COND Vac break	
15 : 02 / 15 : 28		<b>Rx no criticality confirmed</b>	
15 : 07		RCIC startup 15:07 injection started / trip(L-8)	
15 : 15		RHR(A) S/C cooling 15:25 S/C spray IN.	
15 : 16		H2 injection isolation H2O2 ?	
15 : 18		CS(B) , R/W? tank room leak ANN in progress	
15 : 20		ANN reset what ANN ?	
15 : 20		electric boiler steam leak	
15 : 21		MTb EOP , sealed oil ESOP startup confirmed ?	
15 : 26		ANN PNL9-5 「D/W HI PRESS」 D/W HVH additional startup.	
15 : 27		RCIC injection test line switch Rx level 140m 140cm ?	
15 : 29		RPS MG(A) startup ?	
15 : 31		RPS MG(B) IN service	
15 : 34		ANN 「DC125V A/B earth」 IntakeP/C B in progress.	
15 : 37		ANN 「SW tunnel duct sump level high」 tsunami	
15 : 37		ANN 「RVP sump level high」	
15 : 39		D/G 2A "trip" D/G 2A ground	
15 : 40		ANN 「D/G storm sump level high」 D/G 2A storm sump levelhigh ?	
15 : 41		D/G 2B breaker "open" running standby	
15 : 42		M/C 2E "trip" <b>SBO</b>	
		Unit 2 After the earthquake, notes regarding scrum operation is copied from the main control room whiteboard memo. Refer to "after the earthquake operator task handover journal memo".	
Notes on classification		M: MRF issued N: Non compliant report R: Regular Test·Switching O: Operation P: PTW RW:R/W related Mon: Monitoring Others: Others	









現場  
検査

MSV	23.00	1.20
松の木下・南	0.5	0.3
" 北	1.2	0.8

0.45?  
3.10?

13.09.1 3:19 8762 \*\*\*

23.09.1 4:27

Parc 138

121-701  
472H

1.03



(A) 130

3.50

14 T35 30°C

15°50' 沿河高水位測量 H.S2.700

15'53' 註明連絡.

15'41 水位 2.62m - 90cm 壓油 1.2m

設置

① DD FP - ラ=7.25.1.7.3

15'55'

T/B 地下全水位. (注下) 82mm  
○ 1/10 不動鉛垂線、木板等 42mm

SWPP (1) 水位

CWP (2) 水位  
- 140cm ~

16°55' 現場

17. 露 (6°59') 100cm 大地場  
水位不明 (150cm WD) 100cm

17'19' 距離確認

17'19' 5122 (● 高 68.11) 100cm

17'30' DD FP 距離確認 (距離不明) 100cm

17'37' T/B 距離 7.0 ± 20cm < 距離 距離誤差 7.03 100cm

24

17'27' 测量. 17-40 100cm 高度 6.32.  
17'35' "

15'50' 27 测量源水口 水位 7.0m

S/B AD 水口 射水. 中庭内設面積 162m<sup>2</sup>

RCU 14  
射水方法

厚壁管第10条完全

15'58' トランク管 H.1.4m (通水)

16'03' ANN NSSS 等温管失

16'20' EO P ③ STOP

水位

23 PG 可: ✓ M/C 水位 250 cm


16'36' 厚壁管 15条 完成

17'35' ESS 100

水深 80cm  
水深 25cm 不变

17'16' 23 中株旺明計

X'PK 距離 30cm  
X'PK  
X'PK + 2 = 7  
243  
X'PK 水位



3  
17<sup>時</sup> D/FP 燃料 272L → 鋼油栓引抜不可  
(ハサキ)

17<sup>時</sup> 周回部(車輪)の各部隙間 1.2mm 超出不可。  
(ハサキ)

17<sup>時</sup> I.C. 純油吸収基材を2枚貼り上昇開始。 300 rpm

17<sup>時</sup> 給電 + S. 新福島ダム・ジオ. / 1.2m 重ねきひい道路。  
△ 断面M-3 レンジ - 250.

18<sup>時</sup> I.C.(2) 系. 2A. 3A 同 / 三又先生確認

18<sup>時</sup> " 3A 同

18<sup>時</sup> 10T/8大物搬入D. 人孔部位に穴、管路取扱いに注意。  
PS/S 使用不可。

18<sup>時</sup> 大車移動開始

19<sup>時</sup> 高電圧車 → 2SA 变電機起動中。

設置: 15M/C (m位水上升 筐内充水)


M/C A. B. C. D.

P/C A. B.

P/C C. D. (M/C)

DC 電同様 125V

20<sup>時</sup> D/FP.



23 17時 5時22分 20時 0時50分.  
P34' 0時40分 5時50分後

9本 17時 7時 12時 1時  
東北電力給電から → 工場送電(東北電力)  
① 球磨川

D/FP起動後 → I.C.(2) MCB.

T.C. 5時 14時 3時 ✓  
3時 3時 2時  
MCB

新福島側 工場送電 12cm 462m

8時 2時 + 位監視不可。

14時 3時 3時 3時

- 1B P/G 水  
- 1A P/G 管 1m 50cm 2.525m 2cm.

20時 3時

SRV 由/由/卷

• 4.7±7.0 MPa, PI60A

• 水位 -140cm L-DS

• 0.7/0.7MPa 30KPa

FL P/ 2cm

M/C < B - 2  
M/C 2c - 2

23 M/C 2A 2B 2c 2D 2E

20°40' 9/6 PP CS 駆し. お湯なし

20°50' 9/6 PP 駆動 21°00'

21°08' 9/6 (駆動動作) - (重音) / 游泳  
- 21°11' 駆動動作?

現場  
+2.5

電話 A - 227 使用不可 (10.24 - 0.8m)

21°51' 15 BB 入域 禁止

1000 CPS

21°11' 水位計 OS 確認. ④ +60 cm  
A 9/11. OS  
↑  
21°16' 227 元箱 1箱

21°13' +30 cm ±1.5

21°21' 塑料袋 14個 10.24 +30 cm +40

(B) 水位計 1000 CPS

21°32' +30 cm  
+50 cm

+45 cm  
④ IC

21°30' IC  
3A FWD

21:57 ④ +55 cm

22:12 " 59 "

22:16 ④ (2a)

22:16 59 cm 22:45 59  
22:23 59 cm 23:19 59

ACU 100

M125 B. F. 029.13

(総量計 2113)

22:16

● ● ● (2) 10.27 A 227

22:22 MP 7 TD 45 7  
" 8 TD 45 7

164  
39  
25

10 2a  
2 10 4  
2 25

2.7 10 4

4.1

4<sup>15</sup> 中換入口付面 0.65 mSV/H + KURE HAB EP? - 湿潤  
DN 15 (4x/組 x 2) 10,000

4<sup>30</sup> 現場作業禁止、津波、警報表示。

4<sup>20</sup>~5<sup>00</sup> RCIC DA 1.4: 0.75E → S6.

6<sup>14</sup>~  
6<sup>26</sup> 消火栓引込注入準備 (●, ●, ●)  
1m3 注入開始

6<sup>27</sup>~6<sup>29</sup> " 1000ℓ — Reviv (A130 E5T)

(DN15) 0.75 MPa.

9<sup>04</sup>~9<sup>15</sup> ① 20m/s 25m/s S/C 北西~北東, 東~南東 外  
9<sup>24</sup>~9<sup>32</sup> ② 8.9 9.5 R/B 2FL SHCHK 室上部  
— ③

10<sup>16</sup> PCV付 AO-160-90 開操作 X

10<sup>24</sup> "

PCV付 AO-160-90 開操作 X

企画会議

1U

→ 43 電流

$$(V-1) \div 4 \times 10^3$$

3U のアラート

3U DOP RUN φ

13 3~2 TIE 全角

PP 压力 0.17 MPa 上限

AM ラインより注入 2-循環器回路

2U RHR SN. DESW 有効性：開ルク - 3.4 kg 水量  
13 100% D-57 実 (13 路引出 管路)

DIN A-1 40-90 度/角 電子回路 ST-BY

1.27.7.21 煙管 DIP -

13 サイ - JA 送入部電源切替

⑥ CTHPP は吸収 2365V AM ライン (PP 開ルク)

本体の吸収ルクを 2365V に変更する  
→ 2365V の水流量を下げる → 2365V の水温を下げる

日付 13.7.21

注：(1) 本体の吸収ルクを 2365V に変更する

→ 2365V の水流量を下げる → 2365V の水温を下げる

15 行核除外時間 (UA 時間) を短くする方法  
あり哉。

2U

RefC 送水速度？

432 3600 L/h


CRD (A) SFR (Ropineau)  
放散装置中

Q: REWE = 3.725 kg  
CROSSD RUN (LSS) (DTP)

$$(1.145-1) \div 4 \times 10^3$$

$$= 3.725 \text{ kg}$$

$\text{kg} \rightarrow \text{m}^3$



JWC

DAE

14' ● ● ● ● ●

1°05' [津波警報発令中]

2°12'

1°30'

FP

2° HTR室 1°53' - ● ● ●  
水位計 2°10'

4° RCIC入力終了 ST → SC

● ● ● ● ● ● ● ● ●

4°3' ● ● ● ●

2°10' ● ● ● ● 2°RCIC.

2°15' 0.84 MPa → 0.74 MPa  
(740 kPa.)

850 kPa  
740 kPa

2°25' 0.84 MPa - S/P圧力

3°15' 危急指示: 津波 侵襲警戒

0.85  
0.26  
±6.0

3°30' 3号 FP起動

4°3' 中核放射線上昇 0.18 → 0.33 μS/h

6°00' 0.74 MPa

1号機 運転日誌  
Unit 1 Operation log

太枠は炉規則第7条／保安規定第120条対象記録

Fukushima Daiichi Nuclear Power Station Unit 1

福島第一原子力発電所 1号機  
運転日誌 [1]

Operation log [1]

2011年10月11日

確認 項目	承認		内 容 檢 診	作成
	当該長	当面副長		
電子領土在籍済者	2 直			原稿なし 記載有り
1-1 直				原稿なし 記載有り
1-2 直				原稿なし 記載有り
2 直				原稿なし 記載有り

9.120		9.13.31					
原子炉に使用している冷却材 及び減速材の毎日の消耗量							
毎日1回	プラント起動前の格納容器閉鎖～プラント停止後の格納容器開放まで						
9	10						
補給水精算記録	格納容器内の原子炉冷却材漏えい率						
純水精栓水基 FO-2-L1 × 100g	D/W床ドレンサンプル流量 FO-2001-432(×0.01m <sup>3</sup> )	D/W排水ドレンサンプル流量 FO-2001-419(×0.01m <sup>3</sup> )	D/W冷却材ドレン量 FO-1602-19(×0.1d)				
空 庫	912						
24			D/W 床ドレン m <sup>3</sup> /h				
0	40808	43177	247538	239434	全庫底量 m <sup>3</sup> /h		
差							
主発電機	東北電等供算 12						
発電出力	起動変圧器			所内変圧器	所内電力量 合計		
V1	IS	2SA	2SB	小計	TA	1B	小計
1kWh × 10,000	kWh × 1,000	kWh × 1,000	kWh × 1,000	MWh	kWh × 1,000	kWh × 1,000	MWh
831	×24	×24	×24		×24	×24	
EI-T02	1S1	2SA1	2SB1		1A2B	1B2	
24.							
0 37	622.6	66 382.0	86 445.0	09 358.0	15 150.0	72 253.0	
差							

$$所内電力量算出  
IS1 + 2SA1 + 2SB1 + 1A2B + 1B2 - (2A9B + 2B2 + \text{集中ラム}) = \text{MW}$$

所内電力量のうち  
基準(1)(2)SA使用分 MWh

2. PTW以外で記録不可な場合は「-」としそのまま記入する。PTWの場合は「PTW」と記入する。  
 3. 記録不可な場合は該当の欄に「/」とする。(記録日就別表の各項目も同様)

Fukushima Daiichi Nuclear Power Station Unit 1

福島第一原子力発電所 1号機

## Operation log [2]

[2] 運転日誌

## 保安規定9条、120条閏連記録

2011年3月11日

炉規則7条／保安規定120条対象記録	
炉規則7条、保安規定120条	原子炉の状態が運転及び起動において1時間ごと
保安規定21条	原子炉の状態が運転及び起動において24時間に1回

附錄  
原子爐  
主任技術者

序号	求解		作成	求解	内需指标		作成
	内需指标	内需指标			内需指标	内需指标	
2 底				1-1 底			
1-2 底				2 底			

二十 別紙

PLANT NAME: FUKUSHIMA DAICHI

OD-7 OPT.3 CONTROL ROD NOTCH POSITIONS (PERIODIC PRINT)

11-MAR-2011 00:00 PRINTED

43	**	**	**	**	**
39	**	**	**	12	**
35	**	**	**	**	**
31	**	**	**	06	**
27	**	**	**	08	**
23	**	12	**	06	**
19	**	**	**	08	**
15	**	**	**	06	**
11	**	**	**	08	**
07				12	**
03				**	**
	02	06	10	14	18
	22	26	30	34	38
	42				

福島第一原子力発電所 1号機 非常用機器状態確認チェックシート

2011年3月11日

	示認 当直員	内審確認 当直勤員	作成 当直員
1 直			
2 直			

項目	通常 状態	2直	1直	項目	通常 状態	2直	1直	項目	通常 状態	2直	1直	記 事
自 動 逃し弁系	A0-95-2	X	V	格納容器 冷却系 [A]	M0-2A	X	V	隔離時 復水器系 [B]	-4B	O	V	
	-95-4	O	V		A0-3001	X	V		-10B	X	V	
	RY-203-3A	X	V		-3002	X	L		-17B-20B	O	L	
	" B	X	V		-3008	X	L		ポンプB	SB	V	
	" C	X	V		-3009	X	L		" D	SB	V	
	" D	X	V		-3010	X	L		M0-25B	X	V	
隔離時 復水器系 [A]	M0-1A	O	V		-3011	X	L		-24B	O	V	
	-2A	O	L		-3012	X	V		--3B	O	V	
	-3A	X	V		-3013	X	V		--4B	X	V	
	-4A	O	V		M0-3	X	L		B系潤滑油ポンプ1B	SB	V	
	-10A	X	V		-4	O	V		" 2B	SB	V	
	-17A-20A	O	V		-5	O	V		" 3B	SB	V	
炉 スプレイ系 [A]	ポンプA	SB	V		-6	O	V		格納容器スプレイポンプC	SB	L	
	" C	SB	L		-8	X	V		" D	SB	L	
	M0-25A	X	L		-9	O	V		M0-4C	O	V	
	-24A	O	L		-10	X	V		-4D	O	V	
	-3A	O	L		-14	X	V		-10B	X	V	
	-4A	X	V		-15	X	V		-11B	X	V	
高 圧 水 系	A系潤滑油ポンプ1A	SB	L		-29	O	V		-13B	X	V	
	" 2A	SB	V		-30	O	V		-30B	O	V	
	" 3A	SB	V		-31	X	V		-1200	X	V	
	格納容器スプレイポンプA	SB	V		-32	X	V		-1201	X	V	
	" B	SB	V		-35	X	V		格納容器冷却海水ポンプC	SB	L	
	M0-4A	O	V		-36	X	L		" D	SB	V	
格納容器 冷却系 [A]	-4B	O	V		-64	X	V		M0-2B	X	V	
	-10A	X	V		-65	X	L		ディーゼル 発電機1A 6.9kVしゃ断器1C1	SB	V	
	-11A	X	V		タービン止め弁(M0弁)	X	V		ディーゼル 発電機1A 6.9kVしゃ断器1D1	O	V	
	-13A	X	L		タービン加減弁(M0弁)	X	V		ディーゼル 発電機1B 6.9kVしゃ断器1D1	SB	V	
	-30A	O	V		AOP	SB	V		ディーゼル 発電機1B 6.9kVしゃ断器1D1	O	V	
	格納容器冷却海水ポンプA	SB	V		海水ポンプ	SB	V		1. 主要操作が終了し、引継ぎまでの間に状態を確認する。 1直帯は18時～引継ぎまで、2直帯は6時～引継ぎまで			
腐 着 時 復 水 器 系 [B]	" B	SB	V		真空ポンプ	SB	V		2. 通常状態と比較し異常なれば「レ」相違する場合は、次の記号で記載する。			
	M0-5A	X	L		流量制御器	AUTO	V		3. 記号 レ：異常なし O：開 X：閉 W：作業中 RUN：運転中 MAN：手動 P/L：引き保持			
	-5B	X	L		M0-1B	O	V					
	-6A	X	V		M0-2B	O	V					
	M0-6B	X	V		-3B	X	V					

2号機 運転日誌  
Unit 2 Operation log

太枠は炉規則第7条／保安規定第120条対象記録

Fukushima Daiichi Nuclear Power Station Unit 2

福島第一原子力発電所 2号機

運転日誌 [1]  
Operation log [1]

2011年3月11日

要求記録範囲(引継ぎ後のプラント状態をチェックする)						
管水 量	原子 炉の 状態	ブール ゲート の状態	原子炉 の加圧	記録用音響 装置	記録が 必要な 項目	
夏利留出力一過渡停止 (実効出力100%)	-	-	-	/	/	1.8.10.11
停電検査中	-	-	-	/	/	1.8.10.12
運転	-	-	-	/	/	1.8.10.13
起動	-	-	-	-	-	1.8.10.14
高圧停止	-	-	-	-	-	1.8.10.15
冷却停止	85°C以上	-	-	加圧なし	-	1.8.10.16
	85°C未満	-	-	加圧	-	1.8.10.17
		-	1体以上 炉心に現 在	開閉	-	1.8.10.18
		-	全燃料 取出中	閉鎖	-	1.8.10.19
		-		開放	-	1.8.10.20
格納容器閉鎖中	-	-	-	/	/	1.8.10.21

記録確認項目

種類	承認	内容確認	作成	記録用紙 データ
原子炉主任技術者	2 直			販売会社 登録
	1-1 直			販売なし 販売有り
	1-2 直			販売なし 販売有り
	2 直			販売なし 販売有り

☆本欄用紙でブルーゲートが開放されている場合はPRA(ストップゲート)の操作を行なう場合はPRA(ストップゲート)と  
同時にPRA(ストップゲート)を止める場合はPRA(ストップゲート)とPRA(ストップゲート)を直角化の変更を行なう。

※の項目に記録要求がある場合でプロセス計算値打ち出しによる差異ができる場合は、算式を使用し  
記録を行なう。

保安機器	9.18.120	9.13.46	9.13.45	9.13.48	28	9.20.27.120	9.120	
炉規則第7条の記録用紙で記録する場合は、記録用紙を複数枚提出する。								
記録すべき 項目を記入	毎日1回	すべての新規	プラント機能の監視用目録 プラント大修中の監視用目録	実効出力一過渡停止	原子炉の状況が運転及び起動において 1時間ごと	原子炉の状況が運転及び起動において 1時間ごと		
項目	1	2	3	4	5	6	7	
時刻	原電子源度 水	サチ ブエ レン ツバ シ ヨー ン ン 度 水 温 度	サチ ブエ レン ツバ シ ヨー ン ン 度 水 温 度	ド詰 ラ系 イ ウ 度	原子炉熱出力	瞬時 1平 均 間 値	原子炉熱出力(補1)	挿ガス再結合器温度
計器	CRS-59-132	LI-18-132	TRS-18-720/B	O2RS-59-75	原子炉 熱出力	原子炉 平均熱出力	( SRNM (APRM) )	A B
PID	-	-	-	S283	S285	-	A C E G B D F H	入口 出口 入口 出口
1	9-4	9-3	9-5	9-25	計算値	9-5	9-34	% °C
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12	6.06	-1.0	15.5	2.60	✓	✓	✓	✓
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								

9.120	9.13.31				
原子炉に使用している冷却材 及び製造材の毎日の補給量					
毎日1回	プラント起動前の格納容器閉鎖～プラント停止後の格納容器開放まで				
8	9				
補給水積算記録	格納容器内の原子炉冷却材漏えい率				
D/W床ドレンサンプ流量 FO-57-100(m³)	D/W床ドレンサンプ流量 FO-20-527(x0.01m³)	D/W冷却材ドレン量 FO-20-530(x0.01m³)	D/W床ドレン m³/h		
場所	9-19	9-19	m³/h		
24					
0	1752.3	40129	103503	176541	全廃棄量 m³/h
差					

主電電機	変圧器等検算
先駆機器	
起動用遮断器	所内変圧器
10	10
跳み	2A 2B 小計
KWh×10,000	KWh×1,000 KWh×1,000 MWh
W-31	メタクラ
WHT-43-107	2A3B 2B2
24	2A1B 2B1
0	63 14 629.0 248.2 31 93 195.0 067.0 32 359.0
差	MWh

所内電力量算出	2A3B+2B2+2A1B+2B1+(WHT-43-108×0.1)+集中ラド+共用所内ボイラー変圧器(2号負荷分)= MWh
所内電力量のうち	所内電力量のうち
集中ラド(2SA)使用分	共用所内ボイラー(2号負荷分)使用分 MWh
記録	文書記録用紙
	被災事項 被1 炉規則第7条、保安規定第120条記録は運転記録のデータである。 被2 原子炉電力量が記載できない場合はは代替記録用紙所により記載する。詳細は運転日誌記録ガイドを確認すること。 被3 再燃湯ポンプ見込温度(原子炉冷却材供給化水人口温度)の各正時の温度と時間別の温度を確認し、温度差が±5°C以上を記載しないことを確認する。
	注記事項(運転日誌用紙) 1. 運転日誌用紙に記載が記載されているものは、BOP打出手書き記録のため、最終打出し記録を確認し データに異常がないかを確認し空欄すること。 2. PTW以外で記録不可な場合は「-」としその理由を記載すること。 3. 記録不要な場合は該記録欄を「/」とする。(運転日誌別紙の手項目も同様)

Fukushima Daiichi Nuclear Power Station Unit 1

福島第一原子力発電所 2号機

## Operation log [2] 運転日誌 [2]

## 保安規定9条、120条關連記錄

炉規則7条／保安規定120条対象記録	
炉規則7条、保安規定120条	原子炉の状態が運転及び起動において1時間ごと
保安規定21条	原子炉の状態が運転及び起動において24時間に1回

2011年3月11日

摘要 原主 任技术指导者	承兑	内部检验	作成	承兑 审查员	内部检验	作成	
	当面承兑	当面副承兑	当面员		当面承兑	当面副承兑	当面员
2 面				1-1 面			
1-2 面				2 面			

## 1 F 2 制御棒位置情報

出力目標

2011/03/11 00:00:00

51			*	*	*	*	*	*	*	*	*	
47			**	**	**	**	**	**	**	**	**	
43		**	10	**	**	**	08	**	**	**	10	**
39		**	**	**	**	**	*	**	**	**	**	**
35	**	**	**	**	10	**	**	**	10	**	**	**
31	**	**	**	**	*	**	**	*	**	**	**	**
27	**	**	08	**	**	**	06	**	**	**	08	**
23	**	**	**	**	*	**	*	**	**	**	**	**
19	**	**	**	**	10	**	**	**	10	**	**	**
15	**	**	**	**	*	**	*	**	**	**	**	**
11	**	10	**	**	**	08	**	**	**	10	**	**
07		**	**	**	**	*	**	**	**	**	**	**
03				*	*	*	*	*	*	*	*	*
02	06	10	14	18	22	26	30	34	38	42	46	50

福島第一原子力発電所 2号機 非常用機器状態確認チェックシート

2011年3月11日

	承認	内容確認	作成
	当直係長	当直副長	当直員
1 直			
2 直			

項目		通常状態	2直	1直	項目		通常状態	2直	1直	項目		通常状態	2直	1直	記事
自 述 し 井 系	A0-2-71A	X	レ		炉心スプレ イ系 (A)	CSポンプA潤滑油ポンプA	S B	レ		残 留 熱 除 去 系 (B)	RHRポンプB系潤滑油ポンプ1B	S B	レ		
	-71B	X	レ			CSポンプA潤滑油予備ポンプA	S B	✓			RHRポンプB系潤滑油ポンプ2B	S B	レ		
	-71C	X	レ			MO-23-15	O	レ			RHRポンプB系潤滑油ポンプ3B	S B	レ		
	-71E	X	レ			-16	O	レ			RHRSポンプB,D潤滑油ポンプB <sub>1</sub>	S B	レ		
	-71G	X	レ			-14	X	✓			RHRSポンプB,D潤滑油ポンプB <sub>2</sub>	S B	レ		
	-71H	X	✓			-17	O	レ			RHRSポンプB,D潤滑油冷却ファンB <sub>1</sub>	S B	レ		
	RHRポンプ A	S B	レ			-57	X	✓			RHRSポンプB,D潤滑油冷却ファンB <sub>2</sub>	S B	✓		
	RHRポンプ C	S B	レ			-58	X	✓			ポンプB	S B	レ		
	RHRSポンプ A	S B	レ			-21	X	✓			MO-14-7B	O	✓		
	RHRSポンプ C	S B	✓			-20	O	レ			-11B	O	レ		
残 留 熱 除 去 系 (A)	MO-10-15A	X	レ			-19	X	レ			-12B	X	レ		
	-15C	X	レ			-24	X	✓			-26B	X	レ		
	-16A	X	レ			-25	X	✓			-5B	O	✓		
	-65A	O	レ			-144	X	✓			CSポンプB潤滑油ポンプB	S B	レ		
	-66A	O	レ			ターピン止め弁	X	✓			CSポンプB潤滑油予備ポンプB	S B	✓		
	-12A	O	レ			ターピン加減弁	X	✓			MO-13-15	O	✓		
	-27A	O	レ			潤滑油ポンプ	S B	✓			-16	O	レ		
	-25A	X	レ			復水ポンプ	S B	✓			-13I	X	✓		
	-31A	X	レ			真空ポンプ	S B	✓			-18	O	レ		
	-26A	X	レ			流量制御器	AUTO	✓			-39	X	✓		
残 留 熱 除 去 系 (B)	-38A	X	レ			RHRポンプB	S B	レ			-41	X	✓		
	-39A	X	レ			RHRポンプD	S B	レ			-20	O	✓		
	-34A	X	✓			RHRSポンプB	S B	✓			-21	X	レ		
	-13A	O	レ			RHRSポンプD	S B	✓			-30	X	✓		
	-13C	O	✓			MO-10-15B	X	✓			-27	X	✓		
	-89A	X	レ			-15D	X	✓			-132	X	✓		
	-20	O	✓			-16B	X	✓			ターピン止め弁	O	✓		
	RHRポンプA系潤滑油ポンプ1A	S B	レ			-65B	O	✓			ターピン加減弁	O	✓		
	RHRポンプA系潤滑油ポンプ2A	S B	レ			-66B	O	レ			復水ポンプ	S B	✓		
	RHRポンプA系潤滑油ポンプ3A	S B	レ			-12B	O	✓			真空ポンプ	S B	✓		
炉 心 ス プレ イ 系 (A)	RHRSポンプA,C潤滑油ポンプA <sub>1</sub>	S B	レ			-27B	O	✓			流量制御器	AUTO	✓		
	RHRSポンプA,C潤滑油ポンプA <sub>2</sub>	S B	レ			-25B	X	✓			ディーゼル発電機	S B	✓		
	RHRSポンプA,C潤滑油冷却ファンA <sub>1</sub>	S B	レ			-31B	X	✓			ディーゼル発電機2A	6.9kvシヤ断器2C3	O	レ	
	RHRSポンプA,C潤滑油冷却ファンA <sub>2</sub>	S B	✓			-26B	X	✓			ディーゼル発電機	S B	✓		
	ポンプA	S B	✓			-32B	X	✓			ディーゼル発電機2B	6.9kvシヤ断器2E2B	O	レ	
	MO-14-7A	O	✓			-39B	X	✓		1. 主要操作が終了し、引継ぎまでの間に状態を確認する。 1直帯は1.8時～引継ぎまで、2直帯は6時～引継ぎまで					
	-11A	O	✓			-34B	X	✓		2. 通常状態と比較し異常なれば「レ」に達する場合は、次の記号で記載する。					
	-12A	X	レ			-13B	O	✓		3. 記号 レ:異常なし O:開 X:閉 W:作業中 RUN:運転中 MAN:手動 P/L:引き保持					
	-26A	X	✓			-13D	O	✓							
	-5A	O	✓			-89B	X	✓							