Situation of water level, transfer and treatment of the accumulated water in Fukushima Daiichi Nuclear Power Station (at 9:00 on March 20)

		Unit 1	Unit 2	Unit 3	Unit 4
Water Level of the accumulated water (at 7:00 on March 20)	Water level of Vertical Shaft	Unmeasurable due to drawdown of water level (Less than O.P.+ 850 mm)	O.P.+ 3,295 mm (12 mm decrease since 5:00 on March 19)	O.P.+ 3,119 mm (11 mm decrease since 5:00 on March 19)	_
	Water level of Turbine Building	O.P.+ 3,383 mm (23 mm increase since 5:00 on March 19)	O.P.+ 3,226 mm (9 mm decrease since 5:00 on March 19)	O.P.+ 3,092 mm (23 mm decrease since 5:00 on March 19)	O.P.+ 3,082 mm (11 mm decrease since 5:00 on March 19)
	Water level of Reactor Building	O.P.+ 4,502 mm (34 mm decrease since 5:00 on March 19)	O.P.+ 3,416 mm (13 mm decrease since 5:00 on March 19)	O.P.+ 3,169 mm (21 mm decrease since 5:00 on March 19)	O.P.+ 3,106 mm (3 mm increase since 5:00 on March 19)
	Water level of each building in the Centralized Radiation Waste	Process Main Building	O.P.+ 5,188 mm (Increase from initial level:6,405 mm, 152 mm increase since 5:00 on March 19)		
		High Temperature Incinerator Building	O.P.+ 2,209 mm (Increase from initial level:2,935 mm, 425 mm decrease since 5:00 on March 19)		
	Treatment Facility	On-site Bunker Building	O.P.+ 4,313 mm (Water level from floor:517 mm, 279 mm decrease since 5:00 on March 19)		
Situation of transfer of the accumulated water		Unit 1	Unit 2 * 1	Unit 3	Unit 4
		_	Basement of Unit 2 Turbine Building →Centralized Radiation Waste Treatment Facility (Process Main Building) Currently being transferred (Since 10:13 on March 18)	Basement of Unit 3 Turbine Building →Centralized Radiation Waste Treatment Facility (High Temperature Incinerator Building) Currently being transferred (Since 8:41 on March 19)	_
		Unit 5 and 6			
		-			
Operation condition of water treatment facility		Cesium Adsorption Apparatus: Since 14:58 on March 16 In operation 2nd Cesium Adsorption Apparatus (Sarry): Since 14:36 on March 16 In operation Water Desalination Apparatus (reverse osmosis membrane): Intermittent operation depending on the water balance Water Desalination Apparatus (evaporative concentration): Intermittent operation depending on the water balance			
Notes	*1: We compared with the data sampled at 5:00 am on March 19, because the water level gauge for the reactor building of Unit 4 and the centralized radiation waste treatment facility has been suspended due to the switchover of power receiving to a temporary M/C (A) of Unit 3/4 of Southside 66 kV switching station. (We usually compare with the data sampled at 4:00pm on March 19).				

For quick publication of the data of water level, values are provided as reference values.