

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 9:00 on October 29)**

Water Level of the accumulated water (at 7:00 on October 29)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Vertical Shaft	Unmeasurable due to drawdown of water level (Less than O.P.+ 850 mm)	O.P.+ 3,315 mm (47 mm increase since 16:00 on October 28)	O.P.+ 3,057 mm (46 mm decrease since 16:00 on October 28)	—
	Water level of Turbine Building	O.P.+ 3,042 mm (15 mm increase since 16:00 on October 28)	O.P.+ 3,320 mm (41 mm increase since 16:00 on October 28)	O.P.+ 2,986 mm (52 mm decrease since 16:00 on October 28)	O.P.+ 2,849 mm (19 mm decrease since 16:00 on October 28)
	Water level of Reactor Building	O.P.+ 4,604 mm (50 mm increase since 16:00 on October 28)	O.P.+ 3,566 mm (53 mm increase since 16:00 on October 28)	O.P.+ 3,158 mm (44 mm decrease since 16:00 on October 28)	O.P.+ 2,866 mm (7 mm decrease since 16:00 on October 28)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 4,824 mm (Increase from initial level:6,041 mm, 1 mm increase since 16:00 on October 28) O.P.+ 3,395 mm (Increase from initial level:4,121 mm, 323 mm increase since 16:00 on October 28) O.P.+ 4,244 mm (Water level from floor:448 mm, 1 mm increase since 16:00 on October 28)		
Situation of transfer of the accumulated water		Unit 1	Unit 2	Unit 3	Unit 4
		—	—	Basement of Unit 3 Turbine Building →Centralized Radiation Waste Treatment Facility (High Temperature Incinerator Building) Currently being transferred (Since 12:18 on October 26)	Basement of Unit 4 Turbine Building →Centralized Radiation Waste Treatment Facility (High Temperature Incinerator Building) Currently being transferred (Since 16:02 on October 24)
		Unit 5 and 6			
		—			
Operation condition of water treatment facility		Cesium Adsorption Apparatus: Since 9:00 on October 3 Suspended 2nd Cesium Adsorption Apparatus (Sarry): Since 14:04 on October 25 In operation Water Desalination Apparatus (reverse osmosis membrane): Intermittent operation depending on the water balance Water Desalination Apparatus (evaporative concentration): Intermittent operation depending on the water balance			
Notes					

※ For quick publication of the data of water level, values are provided as reference values.