

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 18:00 on November 26)**

Water Level of the accumulated water (at 16:00 on November 26)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Vertical Shaft	Unmeasurable due to drawdown of water level (Less than O.P.+ 850 mm)	O.P.+ 3,202 mm (28 mm decrease since 7:00 on November 26)	O.P.+ 3,115 mm (5 mm increase since 7:00 on November 26)	—
	Water level of Turbine Building	O.P.+ 2,653 mm (3 mm increase since 7:00 on November 26)	O.P.+ 3,215 mm (22 mm decrease since 7:00 on November 26)	O.P.+ 3,028 mm (6 mm increase since 7:00 on November 26)	O.P.+ 2,980 mm (15 mm decrease since 7:00 on November 26)
	Water level of Reactor Building	O.P.+ 4,396 mm (6 mm increase since 7:00 on November 26)	O.P.+ 3,484 mm (17 mm decrease since 7:00 on November 26)	O.P.+ 3,203 mm (11 mm increase since 7:00 on November 26)	O.P.+ 2,989 mm (5 mm decrease since 7:00 on November 26)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 4,294 mm (Increase from initial level:5,511 mm, 2 mm increase since 7:00 on November 26) O.P.+ 1,808 mm (Increase from initial level:2,534 mm, 74 mm increase since 7:00 on November 26) O.P.+ 4,260 mm (Water level from floor:464 mm, No change since 7:00 on November 26)		
Situation of transfer of the accumulated water		Unit 1	Unit 2	Unit 3	Unit 4
		—	Basement of Unit 2 Turbine Building →Basement of Unit 3 Turbine Building Currently being transferred (Since 10:14 on November 25)	Basement of Unit 3 Turbine Building →Centralized Radiation Waste Treatment Facility (High Temperature Incinerator Building) Currently being transferred (Since 10:15 on November 23)	Basement of Unit 4 Turbine Building →Centralized Radiation Waste Treatment Facility (High Temperature Incinerator Building) Currently being transferred (Since 9:51 on November 26)
		Unit 5 and 6			
		—			
Operation condition of water treatment facility		Cesium Adsorption Apparatus: Since 9:00 on October 3   Suspended 2nd Cesium Adsorption Apparatus (Sarry): Since 17:57 on November 22   In operation Water Desalination Apparatus (reverse osmosis membrane): Intermittent operation depending on the water balance Water Desalination Apparatus (evaporative concentration): Intermittent operation depending on the water balance			
Notes					

For quick publication of the data of water level, values are provided as reference values.