

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 9:00 on November 22)**

| | | | | | |
|--|---|---|---|---|---|
| Water Level of the accumulated water (at 7:00 on November 22) | | Unit 1 | Unit 2 | Unit 3 | Unit 4 |
| | Water level of Vertical Shaft | Unmeasurable due to drawdown of water level (Less than O.P.+ 850 mm) | O.P.+ 3,242 mm (38 mm increase since 16:00 on November 21) | O.P.+ 2,862 mm (21 mm decrease since 16:00 on November 21) | — |
| | Water level of Turbine Building | O.P.+ 2,728 mm (4 mm increase since 16:00 on November 21) | O.P.+ 3,219 mm (33 mm increase since 16:00 on November 21) | O.P.+ 2,830 mm (23 mm decrease since 16:00 on November 21) | O.P.+ 2,866 mm (22 mm decrease since 16:00 on November 21) |
| | Water level of Reactor Building | O.P.+ 3,950 mm (19 mm increase since 16:00 on November 21) | O.P.+ 3,280 mm (40 mm increase since 16:00 on November 21) | O.P.+ 2,910 mm (23 mm decrease since 16:00 on November 21) | O.P.+ 2,899 mm (16 mm decrease since 16:00 on November 21) |
| | Water level of each building in the Centralized Radiation Waste Treatment Facility | Process Main Building High Temperature Incinerator Building On-site Bunker Building | O.P.+ 4,096 mm (Increase from initial level:5,313 mm, 1 mm increase since 16:00 on November 21) O.P.+ 2,371 mm (Increase from initial level:3,097 mm, 45 mm decrease since 16:00 on November 21) O.P.+ 4,395 mm (Water level from floor:599 mm, 3 mm increase since 16:00 on November 21) | | |
| Situation of transfer of the accumulated water | | Unit 1 | Unit 2 | Unit 3 | Unit 4 |
| | | — | — | Basement of Unit 3 Turbine Building →Centralized Radiation Waste Treatment Facility (High Temperature Incinerator Building) Currently being transferred (Since 9:27 on November 6) | — |
| | | Unit 5 and 6 | | | |
| | | — | | | |
| Operation condition of water treatment facility | | Cesium Adsorption Apparatus: Since 10:12 on November 6 Suspended 2nd Cesium Adsorption Apparatus (Sarry): Since 13:23 on November 21 In operation Water Desalination Apparatus (reverse osmosis membrane): Intermittent operation depending on the water balance Water Desalination Apparatus (evaporative concentration): Intermittent operation depending on the water balance | | | |
| Notes | Since 1:33 PM on September 7, we have been transferring water which has been pumped up from the well point installed at the east side of Unit 2 Turbine Building (coactive pump-up by drain facility) to the Unit 2 Turbine Building. | | | | |

※ For quick publication of the data of water level, values are provided as reference values.