

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 9:00 on October 22)**

Water Level of the accumulated water (at 7:00 on October 22)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Vertical Shaft	Unmeasurable due to drawdown of water level (Less than O.P.+ 850 mm)	O.P.+ 2,858 mm (7 mm decrease since 7:00 on October 21)	O.P.+ 2,659 mm (13 mm increase since 7:00 on October 21)	—
	Water level of Turbine Building	O.P.+ 2,882 mm (30 mm increase since 7:00 on October 21)	O.P.+ 2,836 mm (15 mm decrease since 7:00 on October 21)	O.P.+ 2,872 mm (14 mm increase since 7:00 on October 21)	O.P.+ 2,812 mm (13 mm increase since 7:00 on October 21)
	Water level of Reactor Building	O.P.+ 4,722 mm (43 mm decrease since 7:00 on October 21)	O.P.+ 2,927 mm (14 mm decrease since 7:00 on October 21)	O.P.+ 2,895 mm (16 mm increase since 7:00 on October 21)	O.P.+ 2,820 mm (15 mm increase since 7:00 on October 21)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 3,783 mm (Increase from initial level:5,000 mm, 5 mm increase since 7:00 on October 21) O.P.+ 1,249 mm (Increase from initial level:1,975 mm, 33 mm decrease since 7:00 on October 21) O.P.+ 4,372 mm (Water level from floor:576 mm, 6 mm increase since 7:00 on October 21)		
Situation of transfer of the accumulated water		Unit 1	Unit 2	Unit 3	Unit 4
		—	Basement of Unit 2 Turbine Building →Basement of Unit 3 Turbine Building Currently being transferred (Since 10:46 on October 11)	Basement of Unit 3 Turbine Building →Centralized Radiation Waste Treatment Facility (High Temperature Incinerator Building) Currently being transferred (Since 10:05 on October 11)	—
		Unit 5 and 6			
		Basement of Unit 6 Turbine Building →Temporary Tank Transfer Completed (From 10:00 on October 21 to 15:00 on October 21)			
Operation condition of water treatment facility		Cesium Adsorption Apparatus: Since 9:00 on October 16 Suspended 2nd Cesium Adsorption Apparatus (Sarry): Since 12:41 on October 15 In operation Water Desalination Apparatus (reverse osmosis membrane): Intermittent operation depending on the water balance Water Desalination Apparatus (evaporative concentration): Intermittent operation depending on the water balance			
Notes					

※ For quick publication of the data of water level, values are provided as reference values.