

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 6,2015)**

Water Level of the accumulated water (at 12:00 on October 6)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,659 mm (67 mm increase since 7:00 on October 5)	O.P.+ 2,779 mm (25 mm decrease since 7:00 on October 5)	O.P.+ 3,055 mm (88 mm decrease since 7:00 on October 5)	O.P.+ 3,233 mm (45 mm increase since 7:00 on October 5)
	Water level of Reactor Building	O.P.+ 4,656 mm (115 mm decrease since 7:00 on October 5)	O.P.+ 2,898 mm (65 mm decrease since 7:00 on October 5)	O.P.+ 3,054 mm (219 mm decrease since 7:00 on October 5)	O.P.+ 3,129 mm (40 mm decrease since 7:00 on October 5)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 4,757 mm (118 mm decrease since 7:00 on October 5) O.P.+ 3,268 mm (182 mm increase since 7:00 on October 5) O.P.+ 4,443 mm (2 mm increase since 7:00 on October 5)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.