

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 11,2015)**

Water Level of the accumulated water (at 12:00 on October 11)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,614 mm (26 mm increase since 7:00 on October 10)	O.P.+ 2,794 mm (20 mm decrease since 7:00 on October 10)	O.P.+ 3,008 mm (36 mm decrease since 7:00 on October 10)	O.P.+ 3,176 mm (10 mm decrease since 7:00 on October 10)
	Water level of Reactor Building	O.P.+ 4,566 mm (14 mm decrease since 7:00 on October 10)	O.P.+ 2,911 mm (10 mm decrease since 7:00 on October 10)	O.P.+ 3,012 mm (36 mm decrease since 7:00 on October 10)	O.P.+ 3,076 mm (9 mm decrease since 7:00 on October 10)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 4,167 mm (134 mm decrease since 7:00 on October 10) O.P.+ 3,327 mm (218 mm increase since 7:00 on October 10) O.P.+ 4,452 mm (2 mm increase since 7:00 on October 10)		
Notes					

For quick publication of the data of water level, values are provided as reference values.