

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 12,2015)**

Water Level of the accumulated water (at 12:00 on October 12)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,437 mm (177 mm decrease since 7:00 on October 11)	O.P.+ 2,780 mm (14 mm decrease since 7:00 on October 11)	O.P.+ 2,911 mm (97 mm decrease since 7:00 on October 11)	O.P.+ 3,159 mm (17 mm decrease since 7:00 on October 11)
	Water level of Reactor Building	O.P.+ 4,551 mm (15 mm decrease since 7:00 on October 11)	O.P.+ 2,894 mm (17 mm decrease since 7:00 on October 11)	O.P.+ 2,931 mm (81 mm decrease since 7:00 on October 11)	O.P.+ 3,061 mm (15 mm decrease since 7:00 on October 11)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 4,502 mm (335 mm increase since 7:00 on October 11) O.P.+ 2,446 mm (881 mm decrease since 7:00 on October 11) O.P.+ 4,454 mm (2 mm increase since 7:00 on October 11)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.