

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 13,2015)**

Water Level of the accumulated water (at 12:00 on October 13)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,461 mm (24 mm increase since 7:00 on October 12)	O.P.+ 2,765 mm (15 mm decrease since 7:00 on October 12)	O.P.+ 2,837 mm (74 mm decrease since 7:00 on October 12)	O.P.+ 3,130 mm (29 mm decrease since 7:00 on October 12)
	Water level of Reactor Building	O.P.+ 4,536 mm (15 mm decrease since 7:00 on October 12)	O.P.+ 2,879 mm (15 mm decrease since 7:00 on October 12)	O.P.+ 2,845 mm (86 mm decrease since 7:00 on October 12)	O.P.+ 3,039 mm (22 mm decrease since 7:00 on October 12)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 4,809 mm (307 mm increase since 7:00 on October 12) O.P.+ 1,812 mm (634 mm decrease since 7:00 on October 12) O.P.+ 4,456 mm (2 mm increase since 7:00 on October 12)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.