

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 15,2015)**

Water Level of the accumulated water (at 12:00 on October 15)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,511 mm (20 mm increase since 7:00 on October 14)	O.P.+ 2,720 mm (26 mm decrease since 7:00 on October 14)	O.P.+ 2,933 mm (89 mm increase since 7:00 on October 14)	O.P.+ 3,083 mm (19 mm decrease since 7:00 on October 14)
	Water level of Reactor Building	O.P.+ 4,144 mm (40 mm increase since 7:00 on October 14)	O.P.+ 2,828 mm (30 mm decrease since 7:00 on October 14)	O.P.+ 2,900 mm (72 mm increase since 7:00 on October 14)	O.P.+ 2,990 mm (23 mm decrease since 7:00 on October 14)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 4,644 mm (157 mm decrease since 7:00 on October 14) O.P.+ 2,117 mm (91 mm decrease since 7:00 on October 14) O.P.+ 4,459 mm (2 mm increase since 7:00 on October 14)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.