

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 16,2015)**

Water Level of the accumulated water (at 12:00 on October 16)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,534 mm (23 mm increase since 7:00 on October 15)	O.P.+ 2,709 mm (11 mm decrease since 7:00 on October 15)	O.P.+ 2,932 mm (1 mm decrease since 7:00 on October 15)	O.P.+ 3,090 mm (7 mm increase since 7:00 on October 15)
	Water level of Reactor Building	O.P.+ 4,176 mm (32 mm increase since 7:00 on October 15)	O.P.+ 2,820 mm (8 mm decrease since 7:00 on October 15)	O.P.+ 2,917 mm (17 mm increase since 7:00 on October 15)	O.P.+ 2,989 mm (1 mm decrease since 7:00 on October 15)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 4,475 mm (169 mm decrease since 7:00 on October 15) O.P.+ 2,172 mm (55 mm increase since 7:00 on October 15) O.P.+ 4,461 mm (2 mm increase since 7:00 on October 15)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.