

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 19,2015)**

Water Level of the accumulated water (at 12:00 on October 19)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,379 mm (20 mm increase since 7:00 on October 18)	O.P.+ 2,719 mm (57 mm increase since 7:00 on October 18)	O.P.+ 2,862 mm (28 mm decrease since 7:00 on October 18)	O.P.+ 3,068 mm (11 mm decrease since 7:00 on October 18)
	Water level of Reactor Building	O.P.+ 4,102 mm (56 mm increase since 7:00 on October 18)	O.P.+ 2,793 mm (19 mm increase since 7:00 on October 18)	O.P.+ 2,858 mm (24 mm decrease since 7:00 on October 18)	O.P.+ 2,969 mm (16 mm decrease since 7:00 on October 18)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 4,072 mm (130 mm decrease since 7:00 on October 18) O.P.+ 2,487 mm (191 mm decrease since 7:00 on October 18) O.P.+ 4,292 mm (2 mm increase since 7:00 on October 18)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.