

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 21,2015)**

Water Level of the accumulated water (at 12:00 on October 21)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,417 mm (18 mm increase since 7:00 on October 20)	O.P.+ 2,741 mm (51 mm increase since 7:00 on October 20)	O.P.+ 2,821 mm (23 mm decrease since 7:00 on October 20)	O.P.+ 3,032 mm (20 mm decrease since 7:00 on October 20)
	Water level of Reactor Building	O.P.+ 4,191 mm (36 mm increase since 7:00 on October 20)	O.P.+ 2,814 mm (21 mm increase since 7:00 on October 20)	O.P.+ 2,813 mm (26 mm decrease since 7:00 on October 20)	O.P.+ 2,940 mm (19 mm decrease since 7:00 on October 20)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 4,081 mm (2 mm increase since 7:00 on October 20) O.P.+ 2,495 mm (154 mm decrease since 7:00 on October 20) O.P.+ 4,295 mm (1 mm increase since 7:00 on October 20)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.