

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 22,2015)**

Water Level of the accumulated water (at 12:00 on October 22)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,437 mm (20 mm increase since 7:00 on October 21)	O.P.+ 2,714 mm (27 mm decrease since 7:00 on October 21)	O.P.+ 2,812 mm (9 mm decrease since 7:00 on October 21)	O.P.+ 3,023 mm (9 mm decrease since 7:00 on October 21)
	Water level of Reactor Building	O.P.+ 4,059 mm (132 mm decrease since 7:00 on October 21)	O.P.+ 2,800 mm (14 mm decrease since 7:00 on October 21)	O.P.+ 2,787 mm (26 mm decrease since 7:00 on October 21)	O.P.+ 2,925 mm (15 mm decrease since 7:00 on October 21)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 3,927 mm (154 mm decrease since 7:00 on October 21) O.P.+ 2,905 mm ( 410 mm increase since 7:00 on October 21) O.P.+ 4,297 mm (2 mm increase since 7:00 on October 21)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.