

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 23,2015)**

Water Level of the accumulated water (at 12:00 on October 23)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,456 mm (19 mm increase since 7:00 on October 22)	O.P.+ 2,770 mm (56 mm increase since 7:00 on October 22)	O.P.+ 2,874 mm (62 mm increase since 7:00 on October 22)	O.P.+ 3,018 mm (5 mm decrease since 7:00 on October 22)
	Water level of Reactor Building	O.P.+ 4,094 mm (35 mm increase since 7:00 on October 22)	O.P.+ 2,828 mm (28 mm increase since 7:00 on October 22)	O.P.+ 2,844 mm (57 mm increase since 7:00 on October 22)	O.P.+ 2,917 mm (8 mm decrease since 7:00 on October 22)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 3,777 mm (150 mm decrease since 7:00 on October 22) O.P.+ 2,218 mm (687 mm decrease since 7:00 on October 22) O.P.+ 4,299 mm (2 mm increase since 7:00 on October 22)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.