

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 24,2015)**

Water Level of the accumulated water (at 12:00 on October 24)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,478 mm (22 mm increase since 7:00 on October 23)	O.P.+ 2,744 mm (26 mm decrease since 7:00 on October 23)	O.P.+ 2,848 mm (26 mm decrease since 7:00 on October 23)	O.P.+ 3,021 mm (3 mm increase since 7:00 on October 23)
	Water level of Reactor Building	O.P.+ 4,053 mm (41 mm decrease since 7:00 on October 23)	O.P.+ 2,837 mm (9 mm increase since 7:00 on October 23)	O.P.+ 2,832 mm (12 mm decrease since 7:00 on October 23)	O.P.+ 2,918 mm (1 mm increase since 7:00 on October 23)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 3,568 mm (209 mm decrease since 7:00 on October 23) O.P.+ 2,398 mm ( 180 mm increase since 7:00 on October 23) O.P.+ 4,302 mm (3 mm increase since 7:00 on October 23)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.