

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on October 27,2015)**

Water Level of the accumulated water (at 12:00 on October 27)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	O.P.+ 2,538 mm (20 mm increase since 7:00 on October 26)	O.P.+ 2,770 mm (12 mm decrease since 7:00 on October 26)	O.P.+ 2,854 mm (26 mm decrease since 7:00 on October 26)	O.P.+ 2,996 mm (3 mm decrease since 7:00 on October 26)
	Water level of Reactor Building	O.P.+ 4,026 mm (39 mm decrease since 7:00 on October 26)	O.P.+ 2,849 mm (26 mm increase since 7:00 on October 26)	O.P.+ 2,841 mm (9 mm decrease since 7:00 on October 26)	O.P.+ 2,895 mm (5 mm decrease since 7:00 on October 26)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	O.P.+ 3,157 mm (7 mm increase since 7:00 on October 26) O.P.+ 2,009 mm (139 mm increase since 7:00 on October 26) O.P.+ 4,307 mm (2 mm increase since 7:00 on October 26)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.