

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on March 13,2016)**

		Unit 1	Unit 2	Unit 3	Unit 4
Water Level of the accumulated water (at 12:00 on March 13)	Water level of Turbine Building	T.P.+ 1,296 mm (2 mm increase since 12:00 on March 12)	T.P.+ 1,429 mm (28 mm increase since 12:00 on March 12)	T.P.+ 1,422 mm (No change since 12:00 on March 12)	T.P.+ 1,484 mm (7 mm increase since 12:00 on March 12)
	Water level of Reactor Building	T.P.+ 1,419 mm (7 mm increase since 12:00 on March 12)	T.P.+ 1,505 mm (11 mm increase since 12:00 on March 12)	T.P.+ 1,441 mm (14 mm increase since 12:00 on March 12)	T.P.+ 1,390 mm (5 mm increase since 12:00 on March 12)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 2,574 mm (3 mm increase since 12:00 on March 12) T.P.+ 742 mm (268 mm decrease since 12:00 on March 12) T.P.+ 2,837 mm (13 mm increase since 12:00 on March 12)		
Notes					

For quick publication of the data of water level, values are provided as reference values.