

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on April 27,2016)**

| Water Level of the accumulated water (at 12:00 on April 27) | | Unit 1 | Unit 2 | Unit 3 | Unit 4 |
|---|--|---|---|--|---|
| | Water level of Turbine Building | T.P.+ 1,168 mm (19 mm increase since 12:00 on April 26) | T.P.+ 1,369 mm (2 mm decrease since 12:00 on April 26) | T.P.+ 1,384 mm (15 mm decrease since 12:00 on April 26) | T.P.+ 1,529 mm (No change since 12:00 on April 26) |
| | Water level of Reactor Building | T.P.+ 1,442 mm (3 mm increase since 12:00 on April 26) | T.P.+ 1,461 mm (2 mm decrease since 12:00 on April 26) | T.P.+ 1,398 mm (7 mm decrease since 12:00 on April 26) | T.P.+ 1,416 mm (1 mm increase since 12:00 on April 26) |
| | Water level of each building in the Centralized Radiation Waste Treatment Facility | Process Main Building High Temperature Incinerator Building On-site Bunker Building | T.P.+ 2,156 mm (162 mm decrease since 12:00 on April 26) T.P.+ -86 mm (7 mm increase since 12:00 on April 26) T.P.+ 2,680 mm (No change since 12:00 on April 26) | | |
| Notes | | | | | |

※ For quick publication of the data of water level, values are provided as reference values.