

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on June 11,2016)**

Water Level of the accumulated water (at 12:00 on June 11)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,273 mm (20 mm increase since 12:00 on June 10)	T.P.+ 1,318 mm (39 mm decrease since 12:00 on June 10)	T.P.+ 1,257 mm (39 mm decrease since 12:00 on June 10)	T.P.+ 1,429 mm (3 mm decrease since 12:00 on June 10)
	Water level of Reactor Building	T.P.+ 1,449 mm (62 mm decrease since 12:00 on June 10)	T.P.+ 1,447 mm (38 mm decrease since 12:00 on June 10)	T.P.+ 1,286 mm (16 mm decrease since 12:00 on June 10)	T.P.+ 1,326 mm (1 mm decrease since 12:00 on June 10)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 1,643 mm (72 mm increase since 12:00 on June 10) T.P.+ 538 mm (305 mm increase since 12:00 on June 10) T.P.+ 2,740 mm (191 mm decrease since 12:00 on June 10)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.