

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on June 12,2016)**

Water Level of the accumulated water (at 12:00 on June 12)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,290 mm (17 mm increase since 12:00 on June 11)	T.P.+ 1,338 mm (20 mm increase since 12:00 on June 11)	T.P.+ 1,266 mm (9 mm increase since 12:00 on June 11)	T.P.+ 1,424 mm (5 mm decrease since 12:00 on June 11)
	Water level of Reactor Building	T.P.+ 1,436 mm (13 mm decrease since 12:00 on June 11)	T.P.+ 1,445 mm (2 mm decrease since 12:00 on June 11)	T.P.+ 1,286 mm (No change since 12:00 on June 11)	T.P.+ 1,322 mm (4 mm decrease since 12:00 on June 11)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 1,667 mm (24 mm increase since 12:00 on June 11) T.P.+ 382 mm (156 mm decrease since 12:00 on June 11) T.P.+ 2,698 mm (42 mm decrease since 12:00 on June 11)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.