

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on June 19,2016)**

Water Level of the accumulated water (at 12:00 on June 19)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,233 mm (45 mm decrease since 12:00 on June 18)	T.P.+ 1,379 mm (16 mm increase since 12:00 on June 18)	T.P.+ 1,295 mm (36 mm increase since 12:00 on June 18)	T.P.+ 1,423 mm (4 mm decrease since 12:00 on June 18)
	Water level of Reactor Building	T.P.+ 1,439 mm (57 mm decrease since 12:00 on June 18)	T.P.+ 1,480 mm (16 mm increase since 12:00 on June 18)	T.P.+ 1,303 mm (26 mm increase since 12:00 on June 18)	T.P.+ 1,317 mm (1 mm decrease since 12:00 on June 18)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 1,695 mm (2 mm increase since 12:00 on June 18) T.P.+ 127 mm (312 mm decrease since 12:00 on June 18) T.P.+ 2,772 mm (10 mm increase since 12:00 on June 18)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.