

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on June 20,2016)**

Water Level of the accumulated water (at 12:00 on June 20)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,177 mm (56 mm decrease since 12:00 on June 19)	T.P.+ 1,335 mm (44 mm decrease since 12:00 on June 19)	T.P.+ 1,323 mm (28 mm increase since 12:00 on June 19)	T.P.+ 1,424 mm (1 mm increase since 12:00 on June 19)
	Water level of Reactor Building	T.P.+ 1,442 mm (3 mm increase since 12:00 on June 19)	T.P.+ 1,466 mm (14 mm decrease since 12:00 on June 19)	T.P.+ 1,331 mm (28 mm increase since 12:00 on June 19)	T.P.+ 1,316 mm (1 mm decrease since 12:00 on June 19)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 1,698 mm (3 mm increase since 12:00 on June 19) T.P.+ 108 mm (19 mm decrease since 12:00 on June 19) T.P.+ 2,782 mm (10 mm increase since 12:00 on June 19)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.