

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on June 22,2016)**

Water Level of the accumulated water (at 12:00 on June 22)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,219 mm (20 mm increase since 12:00 on June 21)	T.P.+ 1,359 mm (36 mm increase since 12:00 on June 21)	T.P.+ 1,324 mm (20 mm increase since 12:00 on June 21)	T.P.+ 1,427 mm (2 mm increase since 12:00 on June 21)
	Water level of Reactor Building	T.P.+ 1,492 mm (12 mm decrease since 12:00 on June 21)	T.P.+ 1,456 mm (18 mm increase since 12:00 on June 21)	T.P.+ 1,334 mm (15 mm increase since 12:00 on June 21)	T.P.+ 1,317 mm (No change since 12:00 on June 21)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 1,467 mm (231 mm decrease since 12:00 on June 21) T.P.+ 20 mm (88 mm decrease since 12:00 on June 21) T.P.+ 2,802 mm (20 mm increase since 12:00 on June 21)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.