

**Situation of water level, transfer and treatment of the accumulated water
in Fukushima Daiichi Nuclear Power Station (at 12:00 on June 23,2016)**

Water Level of the accumulated water (at 12:00 on June 23)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,240 mm (21 mm increase since 12:00 on June 22)	T.P.+ 1,323 mm (36 mm decrease since 12:00 on June 22)	T.P.+ 1,309 mm (15 mm decrease since 12:00 on June 22)	T.P.+ 1,429 mm (2 mm increase since 12:00 on June 22)
	Water level of Reactor Building	T.P.+ 1,539 mm (47 mm increase since 12:00 on June 22)	T.P.+ 1,449 mm (7 mm decrease since 12:00 on June 22)	T.P.+ 1,336 mm (2 mm increase since 12:00 on June 22)	T.P.+ 1,316 mm (1 mm decrease since 12:00 on June 22)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building High Temperature Incinerator Building On-site Bunker Building	T.P.+ 1,265 mm (202 mm decrease since 12:00 on June 22) T.P.+ 431 mm (411 mm increase since 12:00 on June 22) T.P.+ 2,812 mm (10 mm increase since 12:00 on June 22)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.