

**Situation of water level, transfer and treatment of the accumulated water  
in Fukushima Daiichi Nuclear Power Station (at 12:00 on June 24,2016)**

Water Level of the accumulated water (at 12:00 on June 24)		Unit 1	Unit 2	Unit 3	Unit 4
	Water level of Turbine Building	T.P.+ 1,262 mm (22 mm increase since 12:00 on June 23)	T.P.+ 1,352 mm (29 mm increase since 12:00 on June 23)	T.P.+ 1,347 mm (38 mm increase since 12:00 on June 23)	T.P.+ 1,430 mm (1 mm increase since 12:00 on June 23)
	Water level of Reactor Building	T.P.+ 1,492 mm (47 mm decrease since 12:00 on June 23)	T.P.+ 1,466 mm (17 mm increase since 12:00 on June 23)	T.P.+ 1,354 mm (18 mm increase since 12:00 on June 23)	T.P.+ 1,317 mm (1 mm increase since 12:00 on June 23)
	Water level of each building in the Centralized Radiation Waste Treatment Facility	Process Main Building  High Temperature Incinerator Building  On-site Bunker Building	T.P.+ 1,119 mm (146 mm decrease since 12:00 on June 23)  T.P.+ 386 mm ( 45 mm decrease since 12:00 on June 23)  T.P.+ 2,827 mm (15 mm increase since 12:00 on June 23)		
Notes					

※ For quick publication of the data of water level, values are provided as reference values.